### DEPARTMENT OF DEFENSE EDUCATION ACTIVITY



# **Department of Defense Dependents Schools - Europe**

## **2003 AHERA** ASBESTOS MANAGEMENT REPORT

## **Heidelberg District Mannheim American Elementary School** Mannheim-Kaefertal, Germany



Prepared by:

Baker Environmental, Inc. A Unit of Michael Baker Corporation

Under Contract with:

U.S. Army Corps of Engineers **Transatlantic Programs Center** 





### DEPARTMENT OF DEFENSE EDUCATION ACTIVITY ASBESTOS MANAGEMENT PROGRAM

### 2003 AHERA Inspection Report

for

### Mannheim American Elementary School Mannheim-Kaefertal, Germany HE 3469

**Prepared For:** 

Department of Defense Education Activity
Logistics Division
4040 North Fairfax Drive
Arlington, Virginia 22203-1635

Prepared By:

Baker Environmental, Inc. Airside Business Park 100 Airside Drive Moon Township, PA 15108



**Under Contract With:** 

U.S. Army Corps of Engineers Transatlantic Programs Center Winchester, Virginia

### 2003 AHERA INSPECTION REPORT FOR MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### **TABLE OF CONTENTS**

#### **IMPORTANT FOREWORD**

#### **SECTIONS**

- 1.0 INTRODUCTION
- 2.0 SUMMARY OF INSPECTION ACTIVITIES
- 3.0 ASSESSMENT AND SAMPLING METHODS
- 4.0 RESULTS OF THE INSPECTION
- 5.0 RECOMMENDED MANAGEMENT ACTIONS

#### **TABLES**

- 4.1 Results of the Inspection
- 5.1 Recommended Management Actions

#### **APPENDICES**

- A AHERA Accreditation Statement and Inspectors' Certificates
- B Glossary
- C Plans of Sample Locations
- D Laboratory Sample Analysis Reports

#### **IMPORTANT FOREWORD**

The information presented in this report satisfies the reporting requirements of the AHERA legislation and DODEA policy regarding asbestos inspections conducted in DODEA facilities worldwide.

Under DODEA Asbestos Management Policy, the principal is the Asbestos Coordinator for this location. Prior to any activity that is likely to disturb building materials, the principal is responsible for ensuring that a thorough review of materials identified in this report has been completed.

FOR A SUMMARY TABULATION OF WHERE ASBESTOS WAS FOUND, AND WHAT SHOULD BE DONE ABOUT IT, PLEASE REFER TO TABLES 4.1 AND 5.1 PRINTED ON BLUE-TINTED PAPER.

Please also note that not all building materials have been tested. Examples of this may be materials which are hidden from view, inaccessible, or where sampling would be destructive. THEREFORE, THERE IS NO ASSURANCE THAT UNTESTED MATERIALS ARE ASBESTOS-FREE.

#### 1.0 INTRODUCTION

As part of the Department of Defense Education Activity (DODEA) Asbestos Management Program, Baker Environmental, Inc. (Baker) has been contracted to inspect each Department of Defense Dependents Schools (DODDS) location for suspected, known, or assumed friable and non-friable asbestos-containing materials (ACM), in accordance with 40 CFR Part 763, Subpart E, the governing regulations of the Asbestos Hazard Emergency Response Act (AHERA). Technical management of the DODEA Asbestos Management Program is being carried out by the U.S. Army Corps of Engineers, Transatlantic Programs Center (USACE-TAC).

In preparation for this inspection, Baker staff reviewed previous asbestos information related to this location and available to Baker.

The inspection included the following activities:

- Identification of all previously known or previously assumed friable and non-friable suspected ACM.
- Identification and sampling, by homogeneous area, of any newly identified suspect ACM.
- Sampling of previously assumed ACM, if accessible.
- An assessment of all suspected, known, or assumed ACM.

Baker provided independent sample analyses under the approved Environmental Protection Agency (EPA) method described in 40 CFR Part 763, Appendix A, Subpart F, by subcontracting the analyses to laboratories accredited in accordance with standards set by the U.S. National Institute of Standards and Technology (NIST) under the National Voluntary Laboratory Accreditation Program (NVLAP).

#### This report provides:

- a summary of inspection activities at this location;
- a description of the assessment and sampling methods employed;
- a table summarizing the results of the inspection and sample analyses; and,
- recommendations for management actions for asbestos materials.

#### The four appendices include:

- a statement of AHERA accreditations and inspector certifications;
- a glossary of terms frequently used throughout the report;
- plans identifying the locations of samples taken during this inspection with room numbers and names used in the tables; and,
- the laboratory sample analysis reports.

#### 2.0 SUMMARY OF INSPECTION ACTIVITIES

The inspection of Mannheim American Elementary School was conducted on 2-8 July 2003, by a Baker field team. Team member names and credentials are in Appendix A.

The following list documents prior asbestos management activities at this location:

Final Survey Report, Mannheim Elementary School, GE 3469, July 1988, by Dynamac Corporation

Pre-Design Report, Mannheim Elementary School, GE 3469, November 1989, by Baker/TSA, Inc.

1991 AHERA Reinspection Report, Mannheim Elementary School, GE 3469, September 1991, by Baker/TSA, Inc.

1994 AHERA Inspection Report, Mannheim Elementary School, GE 3469, by Baker Environmental, Inc.

1997 Triennial Asbestos Resurvey Report, Mannheim Elementary School, GE 3469, by Baker Environmental, Inc.

2000 Triennial Asbestos Resurvey Report, Mannheim Elementary School, HE 3469, by Baker Environmental, Inc.

Baker's field team met with Mr. Don Watts, School Support Technician for Mannheim American Elementary School, at the beginning of the inspection. The following facility utilization was identified:

BUILDING NUMBER (Year Built)	FUNCTION
0697 (Unknown)	Multipurpose
0697K (Unknown)	Kindergarten
ANNEX B (Unknown)	Classrooms

BUILDING NUMBER (Year Built)	FUNCTION
ANNEX C (Unknown)	Classroom/Storage
ANNEX D (Unknown)	Classroom/Storage
ANNEX E (Unknown)	Administration
ANNEX M (Unknown)	Storage

According to Mr. Don Watts, no buildings have been vacated and no new buildings have been occupied since the last AHERA inspection. Building 0697 was renovated since the last AHERA inspection. The renovations involved the partial removal of asbestos-containing vinyl floor tile (Material Number 001) and its adhesive (Material Number 036), as well as the removal of several non asbestos-containing materials. No other renovations or additions have occurred in the buildings that comprise Mannheim American Elementary School since the last AHERA inspection.

At the beginning of this inspection, abatement set-up procedures were observed by the Baker field team in the upstairs classrooms of Wing D. According to the All Star contracting representative, Ms. Ellen Brown, the abatement was to comprise the removal of all flooring materials in all the upstairs classrooms of Wing D. Other abatement procedures were already under way in Room 01 when the Baker field team had arrived. According to Ms. Brown, this abatement was to include flooring materials only. During the course of this inspection, Room 01 was inaccessible to the Baker field team.

In the course of this inspection, 37 suspected or known asbestos-containing homogeneous materials were sampled and/or assessed in the buildings listed above. In addition to sampling and/or assessing the suspected or known asbestos materials, the Baker field team verified the location of previously identified non-asbestos materials. Specific information about each of these materials, including the results of the sample analysis, can be found in Section 4.0 of this report.

In Building 0697, the previous AHERA inspection identified seven ACM: vinyl floor tile (Material Number 001), sheet gasket (Material Number 019), stall partitions (Material Number 021), three types of floor adhesive (Material Number 036, 037, and 041), and wall plaster (Material Number 039). All of the previously identified ACM were located, assessed, and their quantities were confirmed, with the exception of one type of floor adhesive

(Material Number 041). This material is assumed to be present beneath the existing concrete flooring. One stall partition (Material Number 021) is damaged in Room 09D and should be removed. Sixty square feet of this material has also been relocated from one of the toilet rooms to the Old Boiler Room. This material should be removed. The Baker field team identified and sampled 21 additional suspect asbestos materials: vinyl floor sheeting (Material Number 106), six types of floor adhesive (Material Numbers 107, 117, 119, 123, 125, and 126), cove base adhesive (Material Number 108), electrical wire insulation (Material Number 109), two types of ceiling tile (Material Numbers 110 and 114), two types of wallboard (Material Numbers 111 and 113), three types of joint compound (Material Numbers 112, 116, and 124), cement flooring (Material Number 115), sheet gaskets (Material Number 118), rope gasket (Material Number 120), ceiling insulation (Material Number 121), and asphaltic vapor barrier (Material Number 122). The sheet gasket (Material Number 118) and rope gasket (Material Number 120) tested positive for asbestos. All of the other newly sampled materials tested negative for asbestos. To satisfy AHERA sampling requirements, one additional sample of duct insulation (Material Number 007) and five additional samples of exterior plasters were collected (Material Number 009). Both the duct insulation and the exterior plaster samples tested negative for asbestos.

In Building 0697K, the previous AHERA inspection did not identify any ACM. The Baker field team identified and sampled six suspect asbestos materials: sink coating (Material Number 127), sheet gasket (Material Number 128), two types of floor adhesive (Material Numbers 129 and 131), and two types of subfloor material (Material Numbers 130 and 132). The sheet gasket (Material Number 128) tested positive for asbestos. All of the other newly sampled materials tested negative for asbestos.

In Building Annex B, the previous AHERA inspection did not identify any ACM. The Baker field team did not identify any suspect asbestos materials and collected no samples.

In Building Annex C, the previous inspection did not identify any ACM. The Baker field team identified and sampled one suspect asbestos material: sink coating (Material Number 133). The newly sampled material tested negative for asbestos.

In Building Annex D, the previous AHERA inspection did not identify any ACM. The Baker field team did not identify any suspect asbestos materials and collected no samples.

In Building Annex E, the previous AHERA inspection did not identify any ACM. The Baker field team did not identify any suspect asbestos materials and collected no samples.

In Building Annex M, the previous AHERA inspection did not identify any ACM. The Baker field team did not identify any suspect asbestos materials and collected no samples.

#### 3.0 ASSESSMENT AND SAMPLING METHODS

#### Assessment

An assessment was performed by accredited inspectors in conformance with Part 763.88 of the AHERA regulation for inspections [Section 763.85(b)], and guidelines in EPA Publication No. EPA 56015/85-024, "Guidance for Controlling Asbestos-Containing Materials in Buildings" ("The Purple Book") and EPA Publication No. EPA 700/B-92/001 "A Guide to Performing Reinspections Under The Asbestos Hazard Emergency Response Act (AHERA)", for all friable and non-friable known or assumed ACM in each school building at this location. Each homogeneous material was classified into one of the following categories:

- 1. Damaged or Significantly Damaged Thermal System Insulating ACM
- 2. Damaged Friable Surfacing ACM
- 3. Significantly Damaged Friable Surfacing ACM
- 4. Damaged or Significantly Damaged Friable Miscellaneous ACM
- 5. ACM with the Potential for Damage
- 6. ACM with the Potential for Significant Damage
- 7. Any Remaining Friable ACM or Friable Suspected ACM
- N/A Any Remaining Material Assessed and Found to be Not Applicable to Any of the Seven Previous Categories

Definitions of these categories are contained in the glossary (Appendix B).

The inspectors considered the following factors to determine the above classifications:

- Location of Material
- Type of Damage

Friability

- Percent of Damage
- **Overall Condition**

- Amount of Material
- Accessibility
- Influence of Vibration
- Influence of Air Erosion

#### **Sampling**

Each inspector utilized the sampling methodologies described in Part 763.86 of the AHERA regulations, in addition to guidelines described in EPA Publication No. EPA 560/5-85-030a, "Asbestos in Buildings: Simplified Sampling Scheme for Friable Surfacing Materials", and EPA Publication No. EPA 560/5-85-024, "Guidance for Controlling Asbestos-Containing Materials in Buildings", Appendix G. Inaccessible suspect materials were assumed to be asbestos-containing, as provided under the regulations.

Prior to shipment to a United States laboratory, each sample was properly sealed and labeled. Chain-of-custody documentation was sent to the laboratory with the samples.

#### 4.0 RESULTS OF THE INSPECTION

Results of the inspection are presented on Table 4.1. The information on Table 4.1 is presented by building. Within each building, the information is grouped as follows:

- The first group contains all previously identified ACM that were confirmed to be present during the 2003 inspection, and any newly identified ACM.
- The second group contains all previously identified <u>non</u>-asbestos materials that were confirmed to be present during the 2003 inspection, and any new material identified during the 2003 inspection which was determined to be a <u>non</u>-asbestos material by sample analysis.
- The third group contains all previously identified materials, both asbestos and <u>non-asbestos</u>, which could not be confirmed to be present during the 2003 inspection. If the disposition of such material could be determined by the Baker field team, this information was noted in the comments section of Table 4.1.

Headings on Table 4.1 are defined as follows:

**INSPECTION DATE** - Date when this location was visited by a Baker field team to conduct the 2003 inspection.

**BUILDING NUMBER** - Identifies each building included in the report. If the date of construction was known, this information is presented in the parenthesis after the building number.

**HOMO. MATRL. NO. (Homogeneous Material Number)** - Numerical designation assigned to each homogeneous material that is uniform in color and texture, serves the same function, and was installed at the same time.

**MATERIAL TYPE/MATERIAL DESCRIPTION** - Brief description of the material, followed by information on distinguishing characteristics which may include function, size, color, shape, etc., if necessary.

AHERA CAT. (AHERA Category) - SACM-Surfacing Asbestos-Containing Material; TSIACM-Thermal System Insulation Asbestos-Containing Material; MACM-Miscellaneous Asbestos-Containing Material.

**MATERIAL LOCATION(S)** - Material locations as confirmed by the 2003 inspection. The material location(s) can be referenced to the floor plans in Appendix C of this report. The floor plans indicate room numbers and layouts as they existed at the time of the 2003 inspection. If a space within a building was not identified with a room number and materials were determined to be present in that space, the Baker field team assigned the space with a number and recorded this number on the floor plan. Material locations for those materials which could not be confirmed to be present at the time of the 2003 inspection are identified in those rooms where they are believed to have existed.

**QTY.** (Quantity) - Defined as linear footage (LF), square footage (SF), or number of each material contained in a homogeneous area.

**SAMPLE INFORMATION** - Provides information pertinent to the material sample as follows:

- NUMBER A unique identification number assigned to each material sample collected.
- DATE Collection date for the sample.
- RESULT Analytical information provided by the laboratory. For those samples
  which were determined to have asbestos, the percent and type of asbestos is
  identified. The abbreviations used for the analytical results are:

AC = Actinolite CH = Chrysotile

AM = Amosite CR = Crocidolite

AN = Anthophyllite TR = Tremolite

ND = "None Detected" - No asbestos was detected in the sample

The analytical reports for all samples collected during the 2003 inspection are included in Appendix D of this report. Analytical reports for samples collected during previous inspections are included with the historical records for this location.

**FRIABLE** - A material is considered friable if, when dry, it may be crumbled, pulverized, or reduced to powder by hand pressure.

**OVERALL CONDITION** - Overall condition of the material is characterized as follows:

- **UNDAMAGED** The material is in visibly good condition with no apparent damage.
- DAMAGED The material exhibits some damaged areas. In the case of localized damage, less than 25% of the material exhibits damage. In the case of distributed damage, less than 10% of the material exhibits damage.
- SIGNIFICANT DAMAGE The material exhibits extensive damage. In the case of localized damage, equal to or greater than 25% of the material exhibits extensive damage. In the case of distributed damage, equal to or greater than 10% of the material exhibits extensive damage.

If the material is damaged or significantly damaged, the distribution of the damage will be assessed as either Localized (LOCAL) or Distributed (DIST.).

**ACCESS.** (Accessibility) - A rating placed on a material which considers the accessibility for potential contact. It is ranked into one of three categories:

- HIGH The material is readily accessible to building occupants.
- MED The material is not so readily accessible to building occupants.
- LOW The material is not easily accessible to building occupants.

**EPA ASS. CAT. (EPA Assessment Category)** - A damage classification from 1 to 7 as defined by the AHERA for known or suspect ACM:

- 1. Damaged or Significantly Damaged Thermal System Insulating ACM
- 2. Damaged Friable Surfacing ACM
- Significantly Damaged Friable Surfacing ACM
- 4. Damaged or Significantly Damaged Friable Miscellaneous ACM
- 5. ACM with the Potential for Damage
- 6. ACM with a Potential for Significant Damage
- 7. Any Remaining Friable ACM or Friable Suspected ACM
- N/A Any Remaining Material Assessed and Found to be Not Applicable to Any of the Seven Previous Categories

**MANAGEMENT ACTION** - The recommended action based on the EPA assessment category and on the judgement of the inspector based on activities of the occupants. For each asbestos material, at least one of the following management actions pertaining to all or portions of the material will be selected:

- ENCLOSE Installation of an airtight, impermeable, permanent barrier around the ACM.
- **ENCAPSULATE** Treatment of ACM with a penetrating or surface sealant in order to minimize the potential for fiber release.

- O&M A program of work practices to maintain ACM in good condition, ensure clean-up of asbestos fibers previously released, and prevent further release by minimizing and controlling ACM disturbance or damage.
- REMOVE Removal of ACM from a damaged area, a functional space, or a homogeneous area as indicated.
- REPAIR Returning damaged ACM to an undamaged condition.

**COMMENTS** - Additional comments may be provided to further describe the location or condition of materials, clarify sample results, or amplify the recommended management action.

The following table columns contain information only if the material tested positive for asbestos and was confirmed to be present during the 2003 inspection:

Friable

- EPA Assessment Category
- Overall Condition
- Management Action

Accessibility

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	ECCATION(S)	٠. ١.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
THE FOLL	OWING ASBESTOS MAT	ERIALS W	ERE IDENTIFIED IN BUILDING 0697	(Unknown)									
001	VINYL FLOOR TILE (1' X 1' BEIGE WITH WHITE AND BLACK SPECKS)		03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	18,663 SF	11457 11458 11475 11526 11531	04/05/88 04/05/88 04/05/88 04/05/88 04/05/88 04/05/88	2% CH 2% CH 2% CH 2% CH 2% CH 2% CH	NO	UNDAMAGED	нідн	5	O&M	THE ADHESIVE FOR THIS MATERIAL IS MATERIAL IS LOCATED BELOW EXISTING CARPET IN SOME LISTED LOCATIONS. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.
019	SHEET GASKET (2" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	MACM	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICAL ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILER ROOM	222 EA	11463 11465 11507	04/05/88 04/05/88 04/05/88	75% CH 60% CH 30% CH	NO	UNDAMAGED	LOW	5	O&M	
021	STALL PARTITIONS (GRAY CEMENT BOARD)	MACM	GIRLS TOILET G3, OLD BOILER ROOM, 09D	220 SF	11491 11513 11524	04/05/88 04/05/88 04/05/88	30% CH 20% CH 15% CH	NO	DAMAGED / LOCALIZED	HIGH	6	REMOVE O&M	ONE STALL PARTITION IN ROOM 09D IS DAMAGED AND NEEDS TO BE REMOVED. THERE IS ALSO ONE UNINSTALLED STALL PARTITION IN THE OLD BOILER ROOM THAT NEEDS TO BE REMOVED.
036	FLOOR ADHESIVE (BLACK, UNDER 1' X 1' BEIGE WITH WHITE AND BLACK SPECKS VINYL FLOOR TILE)	MACM	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	18,663 SF	0726-MAE-005A 0726-MAE-005B 0726-MAE-005C	07/26/89 07/26/89 07/26/89	3-5% CH 5% CH 3-5% CH	NO	UNDAMAGED	LOW	5	O&M	THIS IS THE ADHESIVE FOR MATERIAL #001. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.
037	FLOOR ADHESIVE (BLACK, UNDER GREEN RAISED DOT RUBBER FLOOR SHEETING)	MACM	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	7,426 SF	0726-MAE-024B 0726-MAE-024C	07/26/89 07/26/89	1-3% CH 1-3% CH	NO	UNDAMAGED	LOW	5	O&M	THIS IS THE ADHESIVE FOR MATERIAL #005.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO.	MATRL. (MATERIAL CAT. LOCATION		MATERIAL LOCATION(S)	QTY.	SAMPLE INFORMATION			FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
039	WALL PLASTER	SACM	CORRIDOR F	250 SF	0726-MAE-009A	07/26/89	ND	NO	UNDAMAGED	HIGH	5	O&M	
	(WHITE)				0726-MAE-009B	07/26/89	ND						
					0726-MAE-009C	07/26/89	1% CH						
					0501-MAE-039A	05/01/91	ND						
					0501-MAE-039B	05/01/91	ND						
					0501-MAE-039C	05/01/91	ND						
					0501-MAE-039D	05/01/91	ND						
					0501-MAE-039E	05/01/91	ND						
041	041 FLOOR ADHESIVE MACN (BROWN GLUE ON BLACK ADHESIVE, UNDER	MACM	CORRIDOR B2	4,576 SF	0501-MAE-041A	05/01/91	1-2% CH	NO	UNDAMAGED	LOW	5	O&M	AT THE TIME OF THE
					0501-MAE-041B	05/01/91	1-2% CH						1997, 2000, AND 2003 AHERA INSPECTIONS,
	GREEN VINYL FLOOR SHEETING)				0501-MAE-041C	05/01/91	<1-2% CH						THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED DUE TO THE APPLICATION OF A NEW CONCRETE FLOORING PRODUCT. IT WAS ASSUMED THAT THIS MATERIAL STILL REMAINS WITHIN THE BUILDING.
118	SHEET GASKET	MACM	09 LOBBY, 27B	18 EA	0703-MAE-118A	07/08/03	70% CH	NO	UNDAMAGED	LOW	5	O&M	THIS MATERIAL IS
	(4" - 6" DIAMETER, GRAY, ON PIPE FLANGE				0703-MAE-118B	07/08/03	70% CH						LOCATED WITHIN THE PIPE CHASE INSIDE 09
	CONNECTIONS)				0703-MAE-118C	07/08/03	70% CH						LOBBY.
120	ROPE GASKET (WHITE)	MACM	MECHANICAL ROOM 3A	1 EA	0703-MAE-120A	07/08/03	50% CH	NO	UNDAMAGED	LOW	5	O&M	THIS MATERIAL IS LOCATED ON PIPING
	(*******L)				0703-MAE-120B	07/08/03	50% CH						AND IS USED AS A
					0703-MAE-120C	07/08/03	50% CH						SPACER FOR CLAMPS.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

НОМО.	MATERIAL TYPE	AHERA	MATERIAL			ATION	FRI- ABLE	OVERALL CONDITION	400500	EPA	MANAGE- MENT	COMMENTS	
MATRL. NO.	(MATERIAL DESCRIPTION)	CAT.	LOCATION(S)	QIY.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	ASS. CAT	ACTION	COMMENTS
THE FOLL	OWING NON-ASBESTOS	MATERIA	LS WERE IDENTIFIED IN BUILDING	0697 (Unkno	own)								
004	CAULK (WHITE)	MACM	EXTERIOR OF BUILDING	55 LF	11456 11478	07/01/88 07/01/88	ND ND						
005	VINYL FLOOR SHEETING (GREEN, RAISED DOT RUBBER FLOOR SHEETING)	MACM	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	7,426 SF	11460 11499	07/01/88 07/01/88	ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #037.
006	FIRE DOOR LINING (WHITE)	MACM	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2	2 EA	11467	07/01/88	ND						
007	DUCT INSULATION (BROWN CORKBOARD)	TSIACM	STAGE CRAWL SPACE	300 SF	11470 11471 0703-MAE-007A	07/01/88 07/01/88 07/08/03	ND ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #124.
009	EXTERIOR PLASTERS (BEIGE, TROWELED-ON)	SACM	EXTERIOR OF BUILDING	185,000 SF	11522 0703-MAE-009A 0703-MAE-009B 0703-MAE-009C 0703-MAE-009D	07/01/88 07/01/88 07/08/03 07/08/03 07/08/03	ND ND ND ND ND						
011	THERMAL PIPE INSULATION (6° - 8° DIAMETER, PLASTER OVER PAPER AND WOOL)	TSIACM	OLD BOILER ROOM	40 LF	0703-MAE-009E 11516 11519 11520 11521	07/08/03 07/01/88 07/01/88 07/01/88	ND ND ND ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	EINFORM/	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(5)	QIT.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
013	FIRE DOOR LINING (PLASTER LINING WITHIN METAL DOOR)	MACM	101A1	1 EA	11474	07/01/88	ND						
017	WALLBOARD (1/2" THICK, GRAY PAPER, WHITE CORE)	MACM	BASEMENT STORAGE ROOM, STORAGE 5, 03, 225CT1, 225CT2, 235DT1, 235DT2	240 SF	11468	07/01/88	ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #096.
018	CEILING ROUGH FINISH			2,500 SF	11464	07/01/88	ND						THIS MATERIAL IS
			DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, STORAGE 5		11466	07/01/88	ND						LOCATED ON CONCRETE CEILING AND COLUMNS.
					11469	07/01/88	ND						CEILING AND COLONING.
					0301-MAE-018A	03/12/01	ND						
					0301-MAE-018B	03/12/01	ND						
023	STAGE CURTAINS (BLACK)	MACM	09 STAGE	725 SF	11493	07/01/88	ND						
025	VINYL FLOOR TILE	MACM	TECHNICAL SUPPORT 1, TECHNICAL	825 SF	11/88	07/01/88	ND						THE 2000 AHERA
025	(10" X 10" BLACK)	WAOW	SUPPORT 2, TECHNICAL SUPPORT	023 01	11489	07/01/88	ND						TRIENNIAL SURVEY
			STORAGE A		11496	07/01/88	ND						TEAM COULD NOT SAMPLE THE ASSOCIATED FLOOR ADHESIVE WITHOUT EXTENSIVE DAMAGE TO THIS FLOOR MATERIAL, THUS, THE FLOOR ADHESIVE FOR THIS MATERIAL WAS UNOBTAINABLE.
026	FIRE DAMPERS	MACM	MAIN CORRIDOR, MECHANICAL ROOM 1, MECHANICAL ROOM 2,	7 EA	11497	07/01/88	ND						THIS MATERIAL IS LOCATED IN THE AIR
	(WHITE)		MECHANICAL ROOM 3A, TECHNICAL		11510	07/01/88	ND						DUCTS.
			SUPPORT 2, 22C, 22D		11511	07/01/88	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE INFORMAT				OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(5)	QIT.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
027	CEILING TILES (2' X 2' WHITE, TEXTURED, SUSPENDED)	MACM	J5, T2, T3, 02, 02A, 02B, 02C, 03, 04, 04A, 04B, 14, 14A, 15, 17, 18	1,400 SF	11500 11501 11505	07/01/88 07/01/88 07/01/88	ND ND ND						
029	VINYL FLOOR TILE (2' X 2' GREEN)	MACM	04	375 SF	11503 11534	07/01/88 07/01/88	ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #072.
032	HEAT SHIELDS (GRAY FIRE PROOF PANELS)	MACM	MECHANICAL ROOM 1, MECHANICAL ROOM 2	4 EA	11508 11509 11512	07/01/88 07/01/88 07/01/88	ND ND ND						THIS MATERIAL IS LOCATED WHERE THE DUCTWORK PENETRATES THE INSIDE WALLS.
042	VINYL FLOOR SHEETING (3' X 3' SQUARES, GRAY WITH WHITE STREAKS)	MACM	07 CAFETERIA	5,250 SF	0194-MAE-042A 0194-MAE-042B 0194-MAE-042C	01/17/94 01/17/94 01/17/94	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #044.
043	VINYL FLOOR SHEETING (BLACK)	MACM	09 STAGE, 09B	1,200 SF	0194-MAE-043A 0194-MAE-043B 0194-MAE-043C	01/17/94 01/17/94 01/17/94	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #044.
044	FLOOR ADHESIVE (TAN, UNDER GRAY WITH WHITE STREAKS AND BLACK VINYL FLOOR SHEETINGS)	MACM	07 CAFETERIA, 09 STAGE, 09B	6,450 SF	0194-MAE-044A 0194-MAE-044B 0194-MAE-044C	01/17/94 01/17/94 01/17/94	ND ND ND						THIS IS THE ADHESIVE FOR MATERIALS #042 AND #043.
045	FLOOR ADHESIVE (TAN, UNDER BROWN CARPET)	MACM	14, 19A, 128C, 232D	4,925 SF	0194-MAE-045A 0194-MAE-045B 0194-MAE-045C	01/17/94 01/17/94 01/17/94	ND ND ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

#### **TABLE 4.1 - RESULTS OF THE INSPECTION**

HOMO.	MATERIAL TYPE	AHERA CAT.		QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI-	OVERALL CONDITION	ACCESS	EPA	MANAGE- MENT	COMMENTS
NO.	(MATERIAL DESCRIPTION)	CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	ASS. CAT	ACTION	COMMENTS
047	CEILING TILES (2' X 2' WHITE, FISSURED, SUSPENDED)	MACM	34	150 SF	0194-MAE-047A 0194-MAE-047B	01/17/94 01/17/94	ND ND						
	,				0194-MAE-047C	01/17/94	ND						
049	FLOOR ADHESIVE (YELLOW, UNDER	SUPPORT 2, 01, 02, 02A, 02B, 02C,	53,770 SF	0726-MAE-006A 0726-MAE-006B	08/11/89 08/11/89	ND ND						THIS IS THE ADHESIVE FOR MATERIAL #067.	
	BROWN, ORANGE, BLUE, LIGHT GREEN, AND GRAY CARPETS)		02D, 11, 32, 33, 121C, 122C, 123C, 124C, 125C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D		0726-MAE-006C	08/11/89	ND						

4 - 11

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO.	ATRL. (MATERIAL CAT. LOCATI	MATERIAL	QTY.	SAMPLE	INFORM!	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS	
NO.	`	CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
	PLASTER (1/16" THICK, SMOOTH SURFACE, WHITE CORE)		CORRIDOR A2, CORRIDOR B1, CORRIDOR B2, CORRIDOR C1, CORRIDOR C2, CORRIDOR D1, CORRIDOR D2, CORRIDOR D1, TOILET G3, J4, J5, K1, K2, K3, K4, MAIN CORRIDOR, STAIRWELL 1, STAIRWELL 10, STAIRWELL 11, STAIRWELL 12, STAIRWELL 13, STAIRWELL 14, STAIRWELL 2, STAIRWELL 3, STAIRWELL 4, STAIRWELL 5, STAIRWELL 6, STAIRWELL 7, STAIRWELL 8, STORAGE C1, STORAGE B3, STORAGE C1, STORAGE C2, STORAGE C3, T21, T22, TECHNICAL SUPPORT 1, TECHNICAL SUPPORT STORAGE A, TECHNICAL SUPPORT		0726-MAE-007B 0726-MAE-007C 0301-MAE-050D 0301-MAE-050E 0301-MAE-050F 0301-MAE-050G	08/11/89 08/11/89 03/09/01 03/09/01 03/09/01	ND ND ND ND ND						
			STORAGE B, 01, 02, 02A, 02B, 02C, 02D, 03, 04, 04A, 04B, 05 SUPPLY, 05A SUPPLY, 07 CAFETERIA, 08, 09 LOBBY, 09 STAGE, 09A, 09B, 09C, 09D, 11, 14, 14A, 15, 17, 18, 19, 19A, 20, 20A, 21, 22 MEDIA CENTER, 22A, 22B, 22C, 22D, 22E, 23, 24, 25, 26, 27, 27B, 28, 28A, 29, 30, 30A, 31, 31A, 32, 33, 34, 101A, 101A1, 102A, 103A, 104A, 105A, 106A, 107A, 108A, 108A1, 109A, 111B, 111B1, 112B, 113B, 114B, 115B, 116B, 117B, 118B, 118B1, 119A, 119B, 121C, 122C, 123C, 124C, 125C, 126C, 127C, 128C, 129C, 131D, 131DA, 132D, 132DB, 134D, 134DT1, 134DT2, 135D, 135DT1, 135DT2, 138D, 134DT1, 135DT2, 139D, 143ES, 201A, 202A, 203A, 204A, 205A, 205AT1, 205AT2, 206A, 207A, 208A, 209A, 211B, 212B, 213B, 214B, 215B, 215BT1, 215BT2, 216B, 217B, 212B, 213B, 214B, 215B, 215B, 215C, 227C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 236D, 237D, 238D, 239D, 131D1, 138D11, 138D11, 138D1										
051	ASPHALTIC ROOFING MATERIALS	MACM	, , ,	45,000 SF	0726-MAE-008A 0726-MAE-008B	08/11/89 08/11/89	ND ND						
	(BLACK)				0726-MAE-008C	08/11/89	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	VAI.	LOOATION(O)	GII.	NUMBER	DATE	RESULT	ABLL	CONDITION	ACCECC.	CAT	ACTION	COMMENT
052	SUBFLOOR MATERIAL	MACM	CORRIDOR F	500 SF	0726-MAE-010A	08/11/89	ND						THIS MATERIAL IS
	(GRAY CONCRETE UNDERLAYMENT)				0726-MAE-010B	08/11/89	ND						LOCATED BELOW EXISTING FLOORING
					0726-MAE-010C	08/11/89	ND						MATERIALS.
053	SUBFLOOR MATERIAL	MACM	CORRIDOR F	500 SF	0726-MAE-011A	08/11/89	ND						THIS MATERIAL IS
	(GRAY CONCRETE UNDERLAYMENT)				0726-MAE-011B	08/11/89	ND						LOCATED BELOW EXISTING FLOORING
					0726-MAE-011C	08/11/89							MATERIALS.
054	FLOOR ADHESIVE	MACM	141E, 143E, 143EK	1,900 SF	0726-MAE-012A	08/11/89	ND						THIS IS THE ADHESIVE
	(YELLOW, UNDER CREAM WITH DARK STREAKS				0726-MAE-012B	08/11/89	ND						FOR MATERIAL #055.
	VINYL FLOOR SHEETING)				0726-MAE-012C	08/11/89	ND						
055	VINYL FLOOR SHEETING	MACM	141E, 143E, 143EK	1,900 SF	0726-MAE-013A	08/09/89	ND						THE ADHESIVE FOR THIS
	(CREAM WITH DARK STREAKS)				0726-MAE-013B	08/09/89	ND						MATERIAL IS MATERIAL #054.
	,				0726-MAE-013C	08/09/89	ND						
056	CARPET	MACM	141E, 143E	875 SF	0726-MAE-014A	08/09/89	ND						THE ADHESIVE FOR THIS
	(BEIGE)				0726-MAE-014B	08/09/89	ND						MATERIAL IS MATERIAL #057.
					0726-MAE-014C	08/09/89	ND						
057	FLOOR ADHESIVE	MACM	141E, 143E	875 SF	0726-MAE-015A	08/09/89	ND						THIS IS THE ADHESIVE
	(TAN, UNDER BEIGE CARPET)				0726-MAE-015B	08/09/89	ND						FOR MATERIAL #056.
	,				0726-MAE-015C	08/09/89	ND						
058	WALL PLASTER	SACM	CORRIDOR E, 141E, 143E	4,000 SF	0726-MAE-016A	08/09/89	ND						
	(WHITE)				0726-MAE-016B	08/09/89	ND						
					0726-MAE-016C	08/09/89	ND						
					0301-MAE-058D	03/12/01	ND						
					0301-MAE-058E	03/12/01	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(3)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
059	FABRIC WALL COVERING	MACM	32, 33	460 SF	0726-MAE-017A	08/09/89	ND						
	(DECORATIVE WALL COATING)				0726-MAE-017B	08/09/89	ND						
	,				0726-MAE-017C	08/09/89	ND						
060	CARPET	MACM	19, 20, 21, 22 MEDIA CENTER, 22A,	7,900 SF	0726-MAE-018A	08/09/89	ND						THE ADHESIVE FOR THIS
	(GREEN)		22C, 23, 24, 25, 26, 28, 29, 30, 31, 31A		0726-MAE-018B	08/09/89	ND						MATERIAL IS MATERIAL #061.
					0726-MAE-018C	08/09/89	ND						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
061	FLOOR ADHESIVE	MACM	19, 20, 21, 22 MEDIA CENTER, 22A,	7,900 SF	0726-MAE-019A	08/09/89	ND						THIS IS THE ADHESIVE
	(YELLOW, UNDER GREEN CARPET)		22C, 23, 24, 25, 26, 28, 29, 30, 31, 31A		0726-MAE-019B	08/09/89	ND						FOR MATERIAL #060.
	2 2.,				0726-MAE-019C	08/09/89	ND						
067	CARPET	MACM	TECHNICAL SUPPORT 1, TECHNICAL	54,600 SF	0726-MAE-023A	08/09/89	ND						THE ADHESIVE FOR THIS
	(BROWN, ORANGE, BLUE, LIGHT GREEN, AND GRAY)		SUPPORT 2, 01, 02, 02A, 02B, 02C, 02D, 11, 32, 33, 121C, 122C, 123C,		0726-MAE-023B	08/09/89	ND						MATERIAL IS MATERIAL #049. NO ADHESIVE IS
			124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D		0726-MAE-023C	08/09/89	ND						ASSOCIATED WITH THIS MATERIAL IN ROOM 128C.
068	VINYL FLOOR SHEETING	MACM	09 GYMNASIUM	4,310 SF	1196-MAE-068A	11/01/96	ND						THE ADHESIVE FOR THIS
	(PURPLE)				1196-MAE-068B	11/01/96	ND						MATERIAL IS MATERIAL #084.
					1196-MAE-068C	11/01/96	ND						#004.
070	FLOOR ADHESIVE	MACM	B1, B2, B3, B4, CORRIDOR A1,	24,070 SF	1196-MAE-070A	11/01/96	ND						
	(YELLOW, UNDER 20" X 20" BLUE WITH VARIOUS		CORRIDOR A2, CORRIDOR B1, CORRIDOR B2, CORRIDOR C1,		1196-MAE-070B	11/01/96	ND						
	COLORED SPECKS RUBBER FLOOR SQUARES)		CORRIDOR C2, CORRIDOR D1, CORRIDOR D2, CORRIDOR F, MAIN CORRIDOR, 09 LOBBY		1196-MAE-070C	11/01/96	ND						
071	SINK COATING	MACM	B1, B2, B3, B4, 19, 20, 21, 22B, 28, 29,	14 EA	1196-MAE-071A	11/01/96	ND						
	(BLACK PAD)		B1, B2, B3, B4, 19, 20, 21, 22B, 28, 29, 30, 132D, 134D		1196-MAE-071B	11/01/96	ND						
					1196-MAE-071C	11/01/96	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO.	MATERIAL HOMO. TYPE AHERA MATRL. (MATERIAL CAT. NO. DESCRIPTION)	AHERA	MATERIAL LOCATION(S)	QTY.	SAMPLE	EINFORM <i>!</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
		CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
072	FLOOR ADHESIVE (YELLOW, UNDER 2' X 2' GREEN VINYL FLOOR TILE)	MACM	04	375 SF	1196-MAE-072A 1196-MAE-072B 1196-MAE-072C	11/01/96 11/01/96 11/01/96	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #029.
073	FLOOR ADHESIVE (YELLOW, UNDER BLUE AND PURPLE RAISED DOT RUBBER FLOORING)	MACM	STAIRWELL 10, STAIRWELL 11, STAIRWELL 12, STAIRWELL 13, STAIRWELL 14, STAIRWELL 2, STAIRWELL 3, STAIRWELL 4, STAIRWELL 5, STAIRWELL 6, STAIRWELL 7, STAIRWELL 8, STAIRWELL 9	5,600 SF	1196-MAE-073A 1196-MAE-073B 1196-MAE-073C	11/01/96 11/01/96 11/01/96	ND ND ND						
074	FLEX CONNECTOR (RED CLOTH)	MACM	MECHANICAL ROOM 3B	1 EA	1196-MAE-074A 1196-MAE-074B 1196-MAE-074C	11/01/96 11/01/96 11/01/96	ND ND ND						
084	FLOOR ADHESIVE (YELLOW, UNDER PURPLE VINYL FLOOR SHEETING)	MACM	09 GYMNASIUM	4,310 SF	1196-MAE-084A 1196-MAE-084B 1196-MAE-084C	11/05/96 11/05/96 11/05/96	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #068.
096	JOINT COMPOUND (WHITE)	MACM	BASEMENT STORAGE ROOM, STORAGE 5, 03, 225CT1, 225CT2, 235DT1, 235DT2	24 SF	0301-MAE-096A 0301-MAE-096B 0301-MAE-096C	03/09/01 03/09/01 03/09/01	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #017.
097	THERMAL PIPE INSULATION (8" DIAMETER, BLACK PAPER COVER)	TSIACM	STAGE CRAWL SPACE	40 LF	0301-MAE-097A 0301-MAE-097B 0301-MAE-097C	03/09/01 03/09/01 03/09/01	ND ND ND						
098	JOINT COMPOUND (WHITE)	MACM	TECHNICAL SUPPORT 1, TECHNICAL SUPPORT 2	60 SF	0301-MAE-098A 0301-MAE-098B 0301-MAE-098C	03/09/01 03/09/01 03/09/01	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #101.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORMA	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(5)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
099	CEILING TILES (2' X 2' WHITE, PINHOLE, SUSPENDED)	MACM	STAIRWELL 14, TECHNICAL SUPPORT 1, TECHNICAL SUPPORT 2	834 SF	0301-MAE-099A 0301-MAE-099B 0301-MAE-099C	03/09/01 03/09/01 03/09/01	ND ND ND						
100	FLOOR ADHESIVE (YELLOW, UNDER BLUE CARPET)	MACM	B1, B2, B3, B4, 111B, 112B, 118B, 119A, 119B, 211B, 212B, 213B, 214B, 215B, 218B, 219B	11,950 SF	0301-MAE-100A 0301-MAE-100B 0301-MAE-100C	03/09/01 03/09/01 03/09/01	ND ND ND						
101	WALLBOARD (WHITE)	MACM	TECHNICAL SUPPORT 1, TECHNICAL SUPPORT 2	600 SF	0301-MAE-101A 0301-MAE-101B 0301-MAE-101C	03/12/01 03/12/01 03/12/01	ND ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #098.
104	WALLBOARD (WHITE)	MACM	04A	150 SF	0301-MAE-104A 0301-MAE-104B 0301-MAE-104C	03/12/01 03/12/01 03/12/01	ND ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #105.
105	JOINT COMPOUND (WHITE)	МАСМ	04A	15 SF	0301-MAE-105A 0301-MAE-105B 0301-MAE-105C	03/12/01 03/12/01 03/12/01	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #104.
106	VINYL FLOOR SHEETING (BLUE MARBLE PATTERN)	MACM	131D, 131DA, 132D, 132DA, 132DB, 134D, 134DA, 135D, 135DA, 135DB, 138D, 138DA, 138DB, 139D	5,614 SF	0703-MAE-106A 0703-MAE-106B 0703-MAE-106C	07/04/03 07/04/03 07/04/03	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #107.
107	FLOOR ADHESIVE (WHITE, UNDER BLUE MARBLE PATTERN VINYL FLOOR SHEETING)	MACM	131D, 131DA, 132D, 132DA, 132DB, 134D, 134DA, 135D, 135DA, 135DB, 138D, 138DA, 138DB, 139D	5,614 SF	0703-MAE-107A 0703-MAE-107B 0703-MAE-107C	07/04/03 07/04/03 07/04/03	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #106.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

номо.	MATERIAL TYPE	AHERA	MATERIAL	OTV	SAMPLE	INFORMA	ATION	FRI-	OVERALL	400500	EPA	MANAGE-	COMMENTS
MATRL. NO.	(MATERIAL DESCRIPTION)	CAT.	LOCATION(S)	QTY.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	ASS. CAT	MENT ACTION	COMMENTS
108	COVE BASE ADHESIVE (WHITE, UNDER 2" GRAY PLASTIC COVE BASE)	MACM	131D, 131DA, 132D, 135D, 135DA, 138D, 138DA, 139D	410 LF	0703-MAE-108A 0703-MAE-108B 0703-MAE-108C	07/04/03 07/04/03 07/04/03	ND ND ND						
109	ELECTRICAL WIRE INSULATION (WHITE)	MACM	OLD BOILER ROOM	15 LF	0703-MAE-109A 0703-MAE-109B 0703-MAE-109C	07/08/03 07/08/03 07/08/03	ND ND ND						THIS MATERIAL IS LOCATED IN THE LOWER LEVEL OF THE OLD BOILER ROOM.
110	CEILING TILES (2' X 2' WHITE, PINHOLE, SUSPENDED)	MACM	131D, 131DA, 131DT1, 131DT2, 132D, 132DA, 132DB, 132DT1, 132DT2, 133D, 134D, 134DA, 134DT1, 134DT2, 135DA, 135DA, 135DB1, 135DT1, 135DT2, 138D, 135DT1, 138DT1, 138DT2, 138DT1, 138DT2, 139D	5,924 SF	0703-MAE-110A 0703-MAE-110B 0703-MAE-110C	07/08/03 07/08/03 07/08/03	ND ND ND						
111	WALLBOARD (1/2" THICK, GREEN PAPER, WHITE CORE)	MACM	131DT1, 131DT2, 132DT1, 132DT2, 134DT1, 134DT2, 135DT1, 135DT2, 138DA, 138DB, 138DT1, 138DT2	1,640 SF	0703-MAE-111A 0703-MAE-111B 0703-MAE-111C	07/08/03 07/08/03 07/08/03	ND ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #112. THIS MATERIAL IS LOCATED BEHIND CERAMIC TILE.
112	JOINT COMPOUND (WHITE)	MACM	131DT1, 131DT2, 132DT1, 132DT2, 134DT1, 134DT2, 135DT1, 135DT2, 138DA, 138DB, 138DT1, 138DT2	164 SF	0703-MAE-112A 0703-MAE-112B 0703-MAE-112C	07/08/03 07/08/03 07/08/03	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #111.
113	WALLBOARD (1/2" THICK, GRAY PAPER, WHITE CORE)	MACM	05 SUPPLY, 05A SUPPLY, 131DA, 132D, 132DA, 132DB, 133D, 134D, 134DA, 135DB, 138DA, 139D	2,600 SF	0703-MAE-113A 0703-MAE-113B 0703-MAE-113C	07/08/03 07/08/03 07/08/03	ND ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #116.
114	CEILING TILES (CARDBOARD-LIKE, PEGBOARD PATTERN, MECHANICALLY FASTENED)	MACM	121C, 133D, 134D, 135D, 139D, 232D, 233D, 234D, 235D, 238D, 239D	1,194 SF	0703-MAE-114A 0703-MAE-114B 0703-MAE-114C	07/08/03 07/08/03 07/08/03	ND ND ND						THIS MATERIAL IS LOCATED ABOVE THE EXISTING CEILING MATERIAL ON THE WINDOW SIDE OF EACH ROOM.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(3)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
115	CEMENT FLOORING	MACM	131DA, 135DA, 138D, 138DA, 139D	1,768 SF	0703-MAE-115A	07/08/03	ND						
	(GRAY, UNDER BLUE MARBLE PATTERN FLOOR				0703-MAE-115B	07/08/03	ND						
	SHEETING)				0703-MAE-115C	07/08/03	ND						
116	JOINT COMPOUND	MACM	05 SUPPLY, 05A SUPPLY, 131DA,	260 SF	0703-MAE-116A	07/08/03	ND						THIS IS THE JOINT
	(WHITE)		132D, 132DA, 132DB, 133D, 134D, 134DA, 135DB, 138DA, 139D		0703-MAE-116B	07/08/03	ND						COMPOUND FOR MATERIAL #113.
			10-1574, 10055, 100574, 1005		0703-MAE-116C	07/08/03	ND						WATERWALE WITO.
117	FLOOR ADHESIVE			324 SF	0703-MAE-117A	07/08/03	ND						
	(TAN, UNDER BLUE CARPET)				0703-MAE-117B	07/08/03	ND						
	CARPET)				0703-MAE-117C	07/08/03	ND						
119	FLOOR ADHESIVE	MACM	101A, 102A, 103A, 104A, 105A, 108A,	1,848 SF	0703-MAE-119A	07/08/03	ND						
	(TAN, UNDER 2' X 2' LAVANDER RUBBER		109A, 201A, 202A, 203A, 204A, 205A, 208A, 209A		0703-MAE-119B	07/08/03	ND						
	FLOOR TILES)				0703-MAE-119C	07/08/03	ND						
121	CEILING INSULATION	MACM	121C, 133D, 134D, 135D, 139D, 232D,	1,194 SF	0703-MAE-121A	07/08/03	ND						THIS MATERIAL IS
	(TAN, CELLULOSE)		233D, 234D, 235D, 238D, 239D		0703-MAE-121B	07/08/03	ND						LOCATED ABOVE THE EXISTING CEILING
					0703-MAE-121C	07/08/03	ND						MATERIAL ON THE WINDOW SIDE OF EACH ROOM.
122	ASPHALTIC VAPOR	MACM	121C, 133D, 134D, 135D, 139D, 232D,	1,194 SF	0703-MAE-122A	07/08/03	ND						THIS MATERIAL IS
	BARRIER (BLACK)		233D, 234D, 235D, 238D, 239D		0703-MAE-122B	07/08/03	ND						LOCATED ABOVE THE EXISTING CEILING
		LACK)			0703-MAE-122C	07/08/03	ND						MATERIAL ON THE WINDOW SIDE OF EACH ROOM.
123	FLOOR ADHESIVE	MACM	TECHNICAL SUPPORT 1	60 SF	0703-MAE-123A	07/08/03	ND						
	(TAN, UNDER LIGHT BLUE WITH DARK BLUE				0703-MAE-123B	07/08/03	ND						
	STREAKS RUBBER FLOOR SHEETING)				0703-MAE-123C	07/08/03	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO.		AHERA	MATERIAL LOCATION(S)	OTV	SAMPLE INFORMATION			FRI- ABLE	OVERALL	ACCESS	EPA ASS.	MANAGE- MENT	COMMENTS
MATRL. NO.	`	CAT.	LOCATION(S)	QTY.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
124	JOINT COMPOUND (GRAY, HARD)	MACM	STAGE CRAWL SPACE	80 LF	0703-MAE-124A 0703-MAE-124B	07/08/03 07/08/03	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #007.
125	FLOOR ADHESIVE (BROWN, UNDER GRAY ANTI-STATIC CARPET)	MACM	113B, 114B, 115B	2,550 SF	0703-MAE-124C 0703-MAE-125A 0703-MAE-125B 0703-MAE-125C	07/08/03 07/08/03 07/08/03 07/08/03	ND ND ND						
126	FLOOR ADHESIVE (YELLOW, UNDER 2' X 2' TAN CARPET SQUARES)	MACM	19A	720 SF	0703-MAE-126A 0703-MAE-126B 0703-MAE-126C	07/08/03 07/08/03 07/08/03	ND ND ND						THIS MATERIAL IS LOCATED ON ALL FOUR WALLS OF THE ROOM.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORMA	TION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	OA!:	Lookiion(o)	<b>Q</b> 11.	NUMBER	DATE	RESULT	ABLL	CONDITION	A00200.	CAT	ACTION	OSIMILITY O
THE FOLLO	WING MATERIALS COL	JLD NOT B	E LOCATED IN BUILDING 0697 (Un	known)									
	STALL PARTITIONS (CEMENT BOARD PARTITIONS)	MACM	108A1	90 SF	ASSUMED ACM 0726-MAE-002A	04/05/88 07/26/89	15% CH						AT THE TIME OF THE 1994 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.
014	HEAT SHIELDS	MACM	STORAGE C3	9 SF	11476 0726-MAE-004A	04/05/88 07/26/89	45% CH ND						AT THE TIME OF THE 1994 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.
	ELECTRICAL WIRE INSULATION (KILN WIRE)	MACM	STORAGE C3	4 SF	11477 0726-MAE-003A	04/05/88 07/26/89	ND 20-25% CH						AT THE TIME OF THE 1994 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.
	WINDOWSILLS (BLACK CEMENT)	MACM	MAIN CORRIDOR	144 SF	11502 11523	04/05/88 04/05/88	10% CH 10% CH						AT THE TIME OF THE 1997 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.
	ROPE GASKET (WHITE CLOTH)	MACM	HEAT DISTRIBUTION ROOM 1	11 LF	1196-MAE-075A 1196-MAE-075B 1196-MAE-075C	11/01/96 11/01/96 11/01/96	70-75% CH 70-75% CH 70-75% CH						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORMA	TION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
HE FOLL	OWING MATERIALS COU	LD NOT B	E LOCATED IN BUILDING 0697 (Un	known)									
002	CEILING TILES (CARDBOARD-LIKE, PEGBOARD PATTERN, GLUED-ON)	MACM	121C, 122C, 123C, 124C, 125C, 128C, 129C, 131D, 132D, 133D, 134D, 135D, 138D, 139D, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	6,100 SF	11454 11459 11480 11530	07/01/88 07/01/88 07/01/88 07/01/88	ND ND ND ND						AT THE TIME OF THE 1997 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
008	FLEX CONNECTOR (BLACK CLOTH)	MACM	MECHANICAL ROOM 3A	3 SF	11472	07/01/88	ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
010	THERMAL PIPE INSULATION (6" - 8" DIAMETER, PLASTER OVER PAPER AND WOOL)	TSIACM	MECHANICAL ROOM 3A	6 LF	11473 0301-MAE-010A 0301-MAE-010B	07/01/88 03/12/01 03/12/01	ND ND ND						AT THE TIME OF THE 2003 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
016	WALLBOARD (WHITE)	MACM	CORRIDOR B1	42 SF	11462 11533	07/01/88 07/01/88	ND ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
020	WALLBOARD (WHITE)	MACM	09 GYMNASIUM	1,000 SF	11490 11498 11537	07/01/88 07/01/88 07/01/88	ND ND ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
024	CEILING TILES (RAISED, MOTTLED PATTERN, SUSPENDED)	MACM	08	40 SF	11494 11495	07/01/88 07/01/88	ND ND						AT THE TIME OF THE 1997 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
030	CEMENT CEILING PANELS (GRAY)	MACM	J5, T2, T3, 01, 03, 04	1,750 SF	11504 11506 11529	07/01/88 07/01/88 07/01/88	ND ND ND						AT THE TIME OF THE 2003 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	E INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
031	WALL AND CEILING PLASTER (TROWELED-ON CEMENT)	SACM	CORRIDOR E	360 SF	11527 11528	07/01/88 07/01/88	ND ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.
033	FABRIC WALL COVERING (TEXTURED PAPER, GRAY CORE)	MACM	BASEMENT STORAGE ROOM	0 SF	11514	07/01/88	ND						AT THE TIME OF THE 1997 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIEI MATERIAL COULD NOT BE LOCATED.
034	BREECHING/STACK INSULATION (BRICK)	TSIACM	OLD BOILER ROOM	1,400 SF	11517 11518	07/01/88 07/01/88	ND ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
035	WALLBOARD (WHITE CHALKY CORE)	MACM	09 GYMNASIUM	30 SF	11535	07/01/88	ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIE MATERIAL COULD NOT BE LOCATED.
038	FLOOR ADHESIVE (BROWN GLUE ON BLACK ADHESIVE, UNDER GREEN FLOOR SHEETING)	MACM	CORRIDOR A2	4,576 SF	0726-MAE-024A 0501-MAE-038A 0501-MAE-038B 0501-MAE-038C	07/26/89 05/01/91 05/01/91 05/01/91	ND <1% CH <1% CH <1% CH						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIEI MATERIAL COULD NOT BE LOCATED.
046	FLOOR ADHESIVE (TAN, UNDER CARPET)	MACM	34	150 SF	0194-MAE-046A 0194-MAE-046B 0194-MAE-046C	01/17/94 01/17/94 01/17/94	ND ND ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIEI MATERIAL COULD NOT BE LOCATED.
064	WALL PLASTER (WHITE)	SACM	CORRIDOR H	20,070 SF	0726-MAE-022A 0726-MAE-022C	08/09/89 08/09/89	ND ND						AT THE TIME OF THE 2000 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697 (Unknown)

HOMO.	MATERIAL TYPE	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	INFORMATION		OVERALL	ACCESS	EPA ASS.	MANAGE- MENT	COMMENTS
MATRL. NO.	(MATERIAL DESCRIPTION)	CAI.	LOCATION(5)	QIY.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
065	VINYL FLOOR SHEETING	MACM	CORRIDOR F	800 SF	0726-MAE-025A 0726-MAE-025B 0726-MAE-025C	08/09/89 08/09/89 08/09/89	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #066. AT THE TIME OF THE 1997 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.
066	FLOOR ADHESIVE (UNDER VINYL FLOOR SHEETING)	MACM	CORRIDOR F	800 SF	0726-MAE-026A 0726-MAE-026B 0726-MAE-026C	08/11/89 08/11/89 08/11/89	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #065. AT THE TIME OF THE 1997 AHERA INSPECTION, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697K (Unknown)

#### **TABLE 4.1 - RESULTS OF THE INSPECTION**

HOMO. MATRL.	(MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE INFORMATION			FRI- ABLE	_	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	CAI.	LOCATION(3)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS

#### THE FOLLOWING ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING 0697K (Unknown)

128	SHEET GASKET	MACM	MR	4 EA 0703-MAE-128A	07/08/03	70% CH	NO	UNDAMAGED	LOW	5	O&M
	(4" DIAMETER, GRAY, ON PIPE FLANGE			0703-MAE-128B	07/08/03	70% CH					
	CONNECTIONS)			0703-MAF-128C	07/08/03	65% CH					

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697K (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM!	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	OAT.	LOGATION(G)	-	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
THE FOLL	THE FOLLOWING NON-ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING 0697K (Unknown)												
062	VINYL FLOOR SHEETING MACM (DARK BLUE, RAISED DOT)		K1A, K2B, K3A, K4B, K5A, K6B, K7A, K8B	423 SF	0726-MAE-020A 0726-MAE-020B 0726-MAE-020C	08/09/89 08/09/89 08/09/89	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #063.
063	FLOOR ADHESIVE (YELLOW, UNDER DARK BLUE, RAISED DOT VINYL FLOOR SHEETING)	MACM	K1A, K2B, K3A, K4B, K5A, K6B, K7A, K8B	423 SF	0726-MAE-021A 0726-MAE-021B 0726-MAE-021C	08/09/89 08/09/89 08/09/89	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #062.
069	VINYL FLOOR SHEETING (LIGHT BLUE)	MACM	ENTRY, K1, K1B, K2, K2A, K3, K3B, K4, K4A, K5, K5B, K6, K6A, K7, K7B, K8, K8A	7,270 SF	1196-MAE-069A 1196-MAE-069B 1196-MAE-069C	11/01/96 11/01/96 11/01/96	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #085.
085	FLOOR ADHESIVE (YELLOW, UNDER LIGHT BLUE VINYL FLOOR SHEETING)	MACM	ENTRY, K1, K1B, K2, K2A, K3, K3B, K4, K4A, K5, K5B, K6, K6A, K7, K7B, K8, K8A	7,270 SF	1196-MAE-085A 1196-MAE-085B 1196-MAE-085C	11/05/96 11/05/96 11/05/96	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #069.
086	WALL PLASTER (WHITE, SMOOTH SURFACE)	SACM	CORRIDOR K, E1, E2, ENTRY, K1, K1A, K1B, K2, K2A, K2B, K3, K3A, K3B, K4, K4A, K4B, K5, K5A, K5B, K6, K6A, K6B, K7, K7A, K7B, K8, K8A, K8B, K9, MR	14,560 SF	0726-MAE-022B 0301-MAE-086A 0301-MAE-086B	08/09/89 03/01/01 03/13/01	ND ND ND						
			IVIR		0301-MAE-086C 0301-MAE-086D 0301-MAE-086E 0301-MAE-086F	03/13/01 03/13/01 03/13/01 03/13/01	ND ND ND ND						
102	FLOOR ADHESIVE (YELLOW, UNDER GRAY CARPET)	MACM	CORRIDOR K	1,350 SF	0301-MAE-102A 0301-MAE-102B 0301-MAE-102C	03/12/01 03/12/01 03/12/01	ND ND ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: 0697K (Unknown)

MATRL.   (MATERIAL DESCRIPTION)   CAT.   LOCATION(S)   QTY.   NUMBER   DATE   RESULT   ABLE   CONDITION   ACCESS.   ASS.   CAT   ACTION	GE- T COMMENTS
(YELLOW, UNDER BROWN CARPET)       0301-MAE-103B       03/12/01       ND         0301-MAE-103C       03/12/01       ND	
CARPET) 0301-MAE-103B 03/12/01 ND 0301-MAE-103C 03/12/01 ND	
0301-MAE-103C 03/12/01 ND	
127 SINK COATING MACM K1, K2, K3, K4, K5, K6, K7, K8, K9 9 EA 0703-MAE-127A 07/08/03 ND	
127 SINK COATING MACM K1, K2, K3, K4, K5, K6, K7, K8, K9 9 EA 0703-MAE-127A 07/08/03 ND	
(BLACK PAD)	
(BLACK PAD) 0703-MAE-127B 07/08/03 ND	
0703-MAE-127C 07/08/03 ND	
129 FLOOR ADHESIVE MACM K1, K2, K3, K4, K8 1,380 SF 0703-MAE-129A 07/08/03 ND (TAN. UNDER GRAY	
CARPET) 0703-MAE-129B 07/08/03 ND	
0703-MAE-129C 07/08/03 ND	
130 SUBFLOOR MATERIAL MACM K1, K2, K3, K4, K8 1,380 SF 0703-MAE-130A 07/08/03 ND	THIS MATERIAL IS
(GRAY, CEMENTITIOUS	UNDER GRAY CARPET.
ÜNDERLAYMENT) 0703-MAE-130B 07/08/03 ND 0703-MAE-130C 07/08/03 ND	
0703-MAE-130C 07/08/03 ND	
131 FLOOR ADHESIVE MACM K5, K6, K7 2,142 SF 0703-MAE-131A 07/08/03 ND	
(TAN, UNDER 2' X 2' DARK BLUE WITH BROWN 0703-MAE-131B 07/08/03 ND	
SPECKS CARPET 0703-MAE-131C 07/08/03 ND	
SQUARES)	
132 SUBFLOOR MATERIAL MACM K5, K6, K7 2,142 SF 0703-MAE-132A 07/08/03 ND	THIS MATERIAL IS
(GRAY, CEMENTITIOUS UNDERLAYMENT) 0703-MAE-132B 07/08/03 ND	UNDER 2' X 2' DARK BLUE WITH BROWN SPECKS
0703-MAE-132C 07/08/03 ND	CARPET SQUARES.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: ANNEX B (Unknown)

номо.		AHERA CAT.	MATERIAL LOCATION(S)					OVERALL	ACCESS	EPA ASS.	MANAGE- MENT	COMMENTS	
MATRL. NO.	DESCRIPTION)	CAI.	LOCATION(S)	QII.	NUMBER	DATE	RESULT	ABLE	CONDITION	ACCESS.	CAT	ACTION	COMMENTS
THE FOLLOWING NON-ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING ANNEX B (Unknown)													
082	VINYL FLOOR SHEETING	MACM	ENTRY 1, ENTRY 2, 311B, 312B	1,810 SF	1196-MAE-082A	11/01/96	ND						THE 1996 INSPECTION
	(BLUE WITH GRAY STREAKS AND WHITE				1196-MAE-082B	11/01/96	ND						TEAM COULD NOT SEPARATE THE FLOOR
	FLOOR ADHESIVE)				1196-MAE-082C	11/01/96	ND						ADHESIVE FROM THE VINYL FLOOR SHEETING, THEREFORE, THE FLOOR ADHESIVE WAS SAMPLED AS PART OF THIS MATERIAL.
083	WALL AND CEILING BOARD	MACM	ENTRY 1, ENTRY 2, 311B, 312B	680 SF	1196-MAE-083A	11/01/96	ND						THE JOINT COMPOUND
	(GRAY SURFACE, WHITE				1196-MAE-083B	11/01/96	ND						FOR THIS MATERIAL IS MATERIAL #087.
	CORE)				1196-MAE-083C	11/01/96	ND						
087	JOINT COMPOUND	MACM	ENTRY 1, ENTRY 2, 311B, 312B	68 SF	0301-MAE-087A	03/09/01	ND						THIS IS THE JOINT
	(WHITE)				0301-MAE-087B	03/09/01	ND						COMPOUND FOR MATERIAL #083.
					0301-MAE-087C	03/09/01	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: ANNEX C (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL DESCRIPTION)	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	<b>5</b> /		4	NUMBER	DATE	RESULT	7.522		7.00200.	CAT	ACTION	
THE FOLLOWING NON-ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING ANNEX C (Unknown)													
			ENTRY 1, ENTRY 2, 321C, 322C	1,810 SF	1196-MAE-079A	11/04/96	ND						THE ADHESIVE FOR THIS
	(LIGHT BLUE WITH GRAY STREAKS VINYL FLOOR				1196-MAE-079B	11/04/96	ND						MATERIAL IS MATERIAL #080.
	SHEETING)				1196-MAE-079C	11/04/96	ND						
000			ENTRY A ENTRY 0 0040 0000	4 040 05	4400 MAE 000A	44/04/00	ND						THIS IS THE ADULES!
	FLOOR ADHESIVE (YELLOW, UNDER LIGHT	MACM	ENTRY 1, ENTRY 2, 321C, 322C	1,810 SF	1196-MAE-080A 1196-MAE-080B	11/04/96 11/04/96	ND ND						THIS IS THE ADHESIVE FOR MATERIAL #079.
	BLUE WITH GRAY STREAKS VINYL FLOOR				1196-MAE-080C	11/04/96	ND ND						
	SHEETING)				1190-WAL-000C	11/04/90	ND						
	WALL AND CEILING	MACM	ENTRY 1, ENTRY 2, 321C, 322C	680 SF	1196-MAE-081A	11/04/96	ND						THE JOINT COMPOUND
	BOARD (WHITE)				1196-MAE-081B	11/04/96	ND						FOR THIS MATERIAL IS MATERIAL #089.
	,				1196-MAE-081C	11/04/96	ND						
	JOINT COMPOUND (WHITE)	MACM	ENTRY 1, ENTRY 2, 321C, 322C	68 SF	0301-MAE-089A	03/09/01	ND						THIS IS THE JOINT COMPOUND FOR
	, ,				0301-MAE-089B	03/09/01	ND						MATERIAL #081.
					0301-MAE-089C	03/09/01	ND						
133	133 SINK COATING N		322C	1 EA	0703-MAE-133A	07/08/03	ND						
	(BLACK PAD)		322C		0703-MAE-133B	07/08/03	ND						
					0703-MAE-133C	07/08/03	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: ANNEX D (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORM <i>A</i>	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	DESCRIPTION!)		NUMBER	DATE	RESULT	ADLL	CONDITION	ACCESS.	CAT	ACTION	COMMENTS	
THE FOLLOWING NON-ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING ANNEX D (Unknown)													
	WALL AND CEILING	MACM	ENTRY 1, ENTRY 2, 333D, 334D	680 SF	1196-MAE-076A	11/01/96	ND						THE JOINT COMPOUND
	BOARD (WHITE)				1196-MAE-076B	11/01/96	ND						FOR THIS MATERIAL IS MATERIAL #090.
					1196-MAE-076C	11/01/96	ND						
			ENTRY 1, ENTRY 2, 333D, 334D	2,080 SF	1196-MAE-077A	11/01/96	ND						THE ADHESIVE FOR THIS
	(LIGHT BLUE WITH GRAY STREAKS)				1196-MAE-077B	11/01/96	ND						MATERIAL IS MATERIAL #091.
	orner mor				1196-MAE-077C	11/01/96	ND						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	FLOOR ADHESIVE	MACM	333D, 334D	150 SF	1196-MAE-078A	11/01/96	ND						
	(YELLOW, UNDER BROWN INTERWOVEN WITH TAN				1196-MAE-078B	11/01/96	ND						
	CARPET)				1196-MAE-078C	11/01/96	ND						
090	JOINT COMPOUND	MACM	ENTRY 1, ENTRY 2, 333D, 334D	68 SF	0301-MAE-090A	03/09/01	ND						THIS IS THE JOINT
	(WHITE)				0301-MAE-090B	03/09/01	ND						COMPOUND FOR MATERIAL #076.
					0301-MAE-090C	03/09/01	ND						WATERIAL #U/6.
091	091 FLOOR ADHESIVE MACM	MACM	ENTRY 1 ENTRY 2 333D 334D	2 080 SE	0301-MAE-091A	03/09/01	ND						THIS IS THE ADHESIVE
	(TAN, UNDER LIGHT BLUE	IVIACIVI	ENTRY 1, ENTRY 2, 333D, 334D 2	2,000 31	0301-MAE-091B	03/09/01	ND						FOR MATERIAL #077.
	WITH GRAY STREAKS VINYL FLOOR SHEETING)				0301-MAE-091C	03/09/01	ND						
					SSS I-IVIAL-US IO	03/03/01	ND						

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: ANNEX E (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL DESCRIPTION)	AHERA CAT.		QTY.	SAMPLE	E INFORMA	ATION	FRI- ABLE		ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)		(4,	·	NUMBER	DATE	RESULT				CAT	ACTION	
THE FOLLOWING NON-ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING ANNEX E (Unknown)													
092	WALLBOARD (GRAY)	MACM	ENTRY 1, ENTRY 2, 331D, 332D	680 SF	0301-MAE-092A 0301-MAE-092B 0301-MAE-092C	03/09/01 03/09/01 03/09/01	ND ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #093.
093	JOINT COMPOUND (WHITE)	MACM	ENTRY 1, ENTRY 2, 331D, 332D	68 SF	0301-MAE-093A 0301-MAE-093B 0301-MAE-093C	03/09/01 03/09/01 03/09/01	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #092.
	VINYL FLOOR SHEETING (LIGHT BLUE WITH GRAY STREAKS)	MACM	ENTRY 1, ENTRY 2, 331D, 332D	2,080 SF	0301-MAE-094A 0301-MAE-094B 0301-MAE-094C	03/09/01 03/09/01 03/09/01	ND ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #095.
095	FLOOR ADHESIVE (TAN, UNDER LIGHT BLUE WITH GRAY STREAKS VINYL FLOOR SHEETING)	MACM	ENTRY 1, ENTRY 2, 331D, 332D	2,080 SF	0301-MAE-095A 0301-MAE-095B 0301-MAE-095C	03/09/01 03/09/01 03/09/01	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #094.

INSPECTION DATE: 2 - 8 JUL 2003 BUILDING NUMBER: ANNEX M (Unknown)

HOMO. MATRL.	MATERIAL TYPE (MATERIAL DESCRIPTION)	AHERA CAT.	MATERIAL LOCATION(S)	QTY.	SAMPLE	INFORMA	ATION	FRI- ABLE	OVERALL CONDITION	ACCESS.	EPA ASS.	MANAGE- MENT	COMMENTS
NO.	DESCRIPTION)	OAI.	Loomion(o)	α	NUMBER	DATE	RESULT	ADLL	CONDITION	A00200.	CAT	ACTION	COMMENTO
THE FOLLOWING NON-ASBESTOS MATERIALS WERE IDENTIFIED IN BUILDING ANNEX M (Unknown)													
	VINYL FLOOR SHEETING (TAN WITH GRAY AND BLACK STREAKS)	MACM	M1, M2, M3, M4	2,500 SF	11481 11487	07/01/88 07/01/88	ND ND						THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #048.
	WALL AND CEILING BOARD (WHITE)	MACM	M1, M2, M3, M4	6,480 SF	11482 11486	07/01/88 07/01/88	ND ND						THE JOINT COMPOUND FOR THIS MATERIAL IS MATERIAL #088.
	ASPHALTIC ROOFING MATERIALS (DARK BROWN, RIGID, FIBERGLASS-LIKE)	MACM	ROOF	2,500 SF	11483 11484	07/01/88 07/01/88	ND ND						
	FLOOR ADHESIVE (YELLOW, UNDER TAN WITH GRAY AND BLACK STREAKS VINYL FLOOR SHEETING)	MACM	M1, M2, M3, M4	2,500 SF	0726-MAE-001A 0726-MAE-001B 0726-MAE-001C	08/11/89 08/11/89 08/11/89	ND ND ND						THIS IS THE ADHESIVE FOR MATERIAL #001.
	JOINT COMPOUND (WHITE)	MACM	M1, M2, M3, M4	648 SF	0301-MAE-088A 0301-MAE-088B 0301-MAE-088C	03/09/01 03/09/01 03/09/01	ND ND ND						THIS IS THE JOINT COMPOUND FOR MATERIAL #002.

#### 5.0 RECOMMENDED MANAGEMENT ACTIONS

Table 5.1 presents recommended management actions for all ACM identified and confirmed to be present during the 2003 inspection. The information on Table 5.1 is grouped by building for each building included in the inventory at the time of the 2003 inspection. Consult the Asbestos Management Plan and the Operations and Maintenance Manual for additional management action information.

#### **TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS**

BUILDING NUMBER	HOMO. MATRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)
0697 (Unknown)	001	VINYL FLOOR TILE (1' X 1' BEIGE WITH WHITE AND BLACK SPECKS)	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #036. THIS MATERIAL IS LOCATED BELOW EXISTING CARPET IN SOME LISTED LOCATIONS. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	019	SHEET GASKET (2" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICAL ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILER ROOM		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	021	STALL PARTITIONS (GRAY CEMENT BOARD)	GIRLS TOILET G3, OLD BOILER ROOM, 09D	ONE STALL PARTITION IN ROOM 09D IS DAMAGED AND NEEDS TO BE REMOVED. THERE IS ALSO ONE UNINSTALLED STALL PARTITION IN THE OLD BOILER ROOM THAT NEEDS TO BE REMOVED.	<ol> <li>PORTIONS OF THIS MATERIAL SHOULD BE REMOVED WITHIN ONE YEAR OF RECEIPT OF THIS REPORT.</li> <li>THIS MATERIAL COULD BE REMOVED BY QUALIFIED MAINTENANCE PERSONNEL WHO HAVE RECEIVED TRAINING IN SMALL SCALE, SHORT DURATION ABATEMENT PROJECTS.</li> <li>FOR THE REMAINDER OF THIS MATERIAL, NO IMMEDIATE ABATEMENT IS REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THE REMAINDER OF THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THE REMAINDER OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	036	FLOOR ADHESIVE (BLACK, UNDER 1' X 1' BEIGE WITH WHITE AND BLACK SPECKS VINYL FLOOR TILE)	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	THIS IS THE ADHESIVE FOR MATERIAL #001. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	037	FLOOR ADHESIVE (BLACK, UNDER GREEN RAISED DOT RUBBER FLOOR SHEETING)	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	THIS IS THE ADHESIVE FOR MATERIAL #005.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	039	WALL PLASTER (WHITE)	CORRIDOR F		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>

#### **TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS**

BUILDING NUMBER	HOMO. MATRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)
0697 (Unknown)	041	FLOOR ADHESIVE (BROWN GLUE ON BLACK ADHESIVE, UNDER GREEN VINYL FLOOR SHEETING)	CORRIDOR B2	AT THE TIME OF THE 1997, 2000, AND 2003 AHERA INSPECTIONS, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED DUE TO THE APPLICATION OF A NEW CONCRETE FLOORING PRODUCT. IT WAS ASSUMED THAT THIS MATERIAL STILL REMAINS WITHIN THE BUILDING.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	118	SHEET GASKET (4" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	09 LOBBY, 27B	THIS MATERIAL IS LOCATED WITHIN THE PIPE CHASE INSIDE 09 LOBBY.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE 0 &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697 (Unknown)	120	ROPE GASKET (WHITE)	MECHANICAL ROOM 3A	THIS MATERIAL IS LOCATED ON PIPING AND IS USED AS A SPACER FOR CLAMPS.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>
0697K (Unknown)	128	SHEET GASKET (4" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	MR		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>

#### APPENDIX A

#### AHERA ACCREDITATION STATEMENT

#### AND


#### **INSPECTORS' CERTIFICATES**

This report was prepared by Baker Environmental, Inc., Coraopolis, Pennsylvania, for the Department of Defense Education Activity (DODEA). The inspection was performed in a manner consistent with applicable regulations and guidelines.

The inspectors who inspected this school are accredited in accordance with Section 206 of Title II under the Asbestos Hazard Emergency Response Act (AHERA). The credentials are copied on the following pages.

William E. Gray

Jefferey C. Kolich





**APPENDIX B** 

**GLOSSARY** 

#### **GLOSSARY**

#### Abatement

Procedures which are implemented to remove asbestos materials from a damaged area, functional space, or a homogeneous area.

#### Asbestos

A group of naturally occurring minerals that can be separated into fibers which are flexible, heat resistant and chemically inert. The following asbestos minerals are used commercially: Actinolite, Amosite, Anthophyllite, Chrysotile, Crocidolite, and Tremolite.

### Asbestos-Containing Material (ACM)

Per EPA regulations, any material that contains more than 1.0 percent asbestos by weight.

#### **Asbestos Coordinator (AC)**

The person at the local level who serves as a focal point or liaison for asbestos activities. Per DODEA Asbestos Management Policy, this person is the Principal of a school, or District Superintendent at a DSO.

## Asbestos Hazard Emergency Response Act (AHERA)

An Act passed by Congress and signed by the President in October 1986 which requires the EPA to promulgate regulations requiring inspections for ACM, development of asbestos management plans, and management actions with respect to friable ACM in U.S. schools including DODDS.

### **Asbestos Management Plan**

Required by AHERA, a plan detailing the steps taken to control potential asbestos hazards in school buildings. **Asbestos Management** 

Program

A program instituted by DODEA to comply with AHERA and to administer long-term control and surveillance of all ACM in school buildings.

**Containment System** 

A separation or barrier system that prevents the movement of asbestos-contaminated air from the abatement work area into uncontaminated areas.

**Encapsulation** 

The treatment of ACM with a penetrating or surface sealant in order to minimize the potential for asbestos fiber release.

**Enclosure** 

The system of containment that creates an airtight seal or barrier between the ACM and the adjacent space.

**EPA** 

**Environmental Protection Agency** 

Friable

Any material which, when dry, may be crumbled, pulverized, or reduced to powder by hand pressure.

Homogeneous Sampling Area

An area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in color or texture, serves the same function, and was installed at the same time.

Removal

The removal of ACM from any surface or component in all or a portion of a building.

Operations and
Maintenance (O&M)
Program

A program specifically designed to clean up asbestos fibers previously released, to prevent the release of fibers by minimizing ACM disturbance or damage, and to monitor the condition of the ACM.

### Surveillance

Periodic inspection of friable and non-friable ACM on a frequency consistent with the requirements of the AHERA regulations.

## APPENDIX C


### **PLANS OF SAMPLE LOCATIONS**


### **Common Spaces**

### **Abbreviations and Designations**


Room abbreviations and designations that may be used on the following sample location drawings are:

BR	-	Boiler Room
E	-	Entry - Exterior side of entry door
ER	-	Electrical Rooms - Includes telephone connection closets or LAN connection rooms
J	-	Janitors Closets - These are small spaces under stairwells and where cleaning supplies are stored
K	-	Kitchen - Includes dishwashing areas
LR	-	Locker Room
MR	-	<b>Mechanical Room</b> - Includes utility rooms and rooms housing air handling units
PC	-	Pipe Chase
SH	-	Shower
SL	-	Stairwell
SY	-	Stairway
Т	-	<b>Toilets</b> - Includes Boys, Girls, Mens, Womens, Staff, Handicapped, and small classroom toilets
V	-	<b>Vestibules</b> - Small lobbies and very short corridors near entrances of buildings





## BUILDING 0697 - WING B - PARTIAL FIRST FLOOR PLAN



BUILDING 0697 PARTIAL FIRST FLOOR PLAN

NOTE:
ONLY SAMPLES TAKEN
DURING THE AHERA
INSPECTION ARE SHOWN.

10' 0' 10' 20' 30' 40'

### LEGEND

II6 Room No.(Typical)

Sample Location

Sample Containing ACM

0203-STU-100


Sample Not Containing ACM

0203-STU-100\*

Sample Not Analyzed

### GENERAL NOTE:

THE FLOOR PLANS ON THIS DRAWING ARE FOR GENERAL ORIENTATION AND CONCEPTUAL PLANNING ONLY. THEY WERE DRAWN FROM A VARIETY OF SOURCES WITHOUT REPRESENTATION AS TO ACCURACY OR SCALE. THEREFORE, THEY ARE NOT SUITABLE FOR DETAILED DESIGN, ENGINEERING, OR CONSTRUCTION USE.



KEY PLAN



SYM	REVISIONS	DATE	APPROVED
			_

## DEPARTMENT OF DEFENSE DEPENDENTS SCHOOLS

Baker

Baker Environmental

A Unit of Michael Baker Corporation

100 Airside Drive Moon Township, PA 1510 U.S. ARMY CORPS OF ENGINEERS TRANSATLANTIC PROGRAMS CENTER



ASBESTOS SAMPLE LOCATIONS
2003 AHERA INSPECTION

Army Corps Engineers

MANNHEIM AMERICAN ELEMENTARY SCHOOL MANNHEIM, GERMANY


HE 3469


BLDG. 0697 – WINGS A, B, E, G, AND H
PARTIAL FIRST FLOOR PLANS


2

SHEET REF. NO.

MED FILE NO.









## ANNEX B - FLOOR PLAN




## ANNEX M - FLOOR PLAN




ANNEX D - FLOOR PLAN



## **BUILDING 0697K - FLOOR PLAN**



## ANNEX C - FLOOR PLAN



## ANNEX E - FLOOR PLAN

NOTE: ONLY SAMPLES TAKEN DURING THE AHERA INSPECTION ARE SHOWN.

10' 0' 10' 20' 30' 40'

### LEGEND

Room No.(Typical)

Sample Location

0203-STU-001 Sample Containing ACM


0203-STU-100 Sample Not Containing ACM

### GENERAL NOTE:

0203-STU-I00\*

THE FLOOR PLANS ON THIS DRAWING ARE FOR GENERAL ORIENTATION AND CONCEPTUAL PLANNING ONLY. THEY WERE DRAWN FROM A VARIETY OF SOURCES WITHOUT REPRESENTATION AS TO ACCURACY OR SCALE. THEREFORE, THEY ARE NOT SUITABLE FOR DETAILED DESIGN, ENGINEERING, OR CONSTRUCTION USE.

Sample Not Analyzed



KEY PLAN

0697



SYM	REVISIONS	DATE	APPROVED
	·		

## DEPARTMENT OF DEFENSE DEPENDENTS SCHOOLS

Baker Environmental
A Unit of Michael Baker Corporation

100 Airside Drive
Moon Township, PA 15108

U.S. ARMY CORPS OF ENGINEERS
TRANSATLANTIC PROGRAMS CENTER



ASBESTOS SAMPLE LOCATIONS
2003 AHERA INSPECTION

Engineers

MANNHEIM AMERICAN ELEMENTARY SCHOOL MANNHEIM, GERMANY HE 3469

ANNEX B, C, D, E & M - FLOOR PLANS,
BUILDING 0697K - FLOOR PLAN

MED FILE NO.

#### APPENDIX D

### LABORATORY SAMPLE ANALYSIS REPORTS

# RJ Lee Group, Inc.

350 Hochberg Road, Monroeville, PA 15146 Phone: (724) 325-1776 Fax: (724) 733-1799

## **Laboratory Report**

Baker Environmental Airside Business Park 100 Airside Drive

Moon Township, PA 15108 Attention: Ms. Donna M. Neal

Telephone: 412-269-6300

Report Date 7/17/2003
Sample Receipt Date. 7/14/2003
RJ Lee Group Job No BAK307036

Client Job No. 101323 1.1/Mannheim E/S HE

3469

Authorization/P.O. No. 101323 1.1

Analysis: Asbestos in Bulk Samples Method: EPA/600/R-93/116

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analy	Analysis st Date
2622067.HPL Description: Ol	0703-MAE-007A live And Black Cork	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622068.HPL Description: Be	0703-MAE-009A eige Plaster	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622069.HPL Description: Be	0703-MAE-009B eige Plaster	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622070.HPL Description: Be	0703-MAE-009C eige Plaster	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622071.HPL Description: Be	0703-MAE-009D eige Plaster	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622072.HPL Description: Be	0703-MAE-009E eige Plaster	Yes	ND	-	100 %	В, М	AKB	7/15/2003

RJ Lee Group Job No:

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622073.HPL Description: Bl	0703-MAE-106A ue Linoleum	Yes	ND	15 CE	85 %	В, М	AKB	7/15/2003
2622074.HPL Description: Bl	0703-MAE-106B ue Linoleum	Yes	ND	15 CE	85 %	В, М	AKB	7/15/2003
2622075.HPL Description: Bl	0703-MAE-106C ue Linoleum	Yes	ND	15 CE	85 %	В, М	AKB	7/15/2003
2622076.HPL Description: W	0703-MAE-107A hite Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622077.HPL Description: W	0703-MAE-107B hite Adhesive	Yes	ND	2 CE	98 %	В, М	AKB	7/15/2003
2622078.HPL Description: W	0703-MAE-107C hite Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622079.HPL Description: Ha	0703-MAE-108A ard White Material	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622080.HPL Description: Ha	0703-MAE-108B ard White Material	Yes	ND	<1 CE	100 %	В, М	AKB	7/15/2003
2622081.HPL Description: Ha	0703-MAE-108C ard White Material	Yes	ND	-	100 %	В, М	AKB	7/15/2003

RJ Lee Group Job No: BA

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622082.HPL Description: E	0703-MAE-109A Black And Tan Woven M	Yes Material	ND	70 CE	30 %	T, B, M	AKB	7/15/2003
2622083.HPL Description: E	0703-MAE-109B Black And Tan Woven M	Yes Iaterial	ND	70 CE	30 %	T, B, M	AKB	7/15/2003
2622084.HPL Description: E	0703-MAE-109C Black And Tan Woven M	Yes Iaterial	ND	70 CE	30 %	Т, В, М	AKB	7/15/2003
2622085.HPL Description: E	0703-MAE-110A Beige Ceiling Tile	Yes	ND	10 CE, 30 FG	60 %	P, B, M	AKB	7/15/2003
2622086.HPL Description: E	0703-MAE-110B Beige Ceiling Tile	Yes	ND	15 CE, 30 FG	55 %	Р, В, М	AKB	7/15/2003
2622087.HPL Description:	0703-MAE-110C Beige Ceiling Tile	Yes	ND	15 CE, 30 FG	55 %	P, B, M	AKB	7/15/2003
2622088.HPL Description: G	0703-MAE-111A Gray Drywall	Yes	ND	5 CE, 2 FG	93 %	B, G, M	AKB	7/15/2003
2622089.HPL Description: C	0703-MAE-111B Gray Drywall	Yes	ND	5 CE, 2 FG	93 %	B, G, M	AKB	7/15/2003
2622090.HPL Description: C	0703-MAE-111C Gray Drywall	Yes	ND	5 CE, 5 FG	90 %	В, G, М	AKB	7/15/2003

RJ Lee Group Job No: BAK307036

Client Job No: 10

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622091.HPL Description: B	0703-MAE-112A eige Joint Compound	Yes	ND	<1 CE	100 %	В, М	AKB	7/15/2003
2622092.HPL Description: B	0703-MAE-112B eige Joint Compound	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622093.HPL Description: B	0703-MAE-112C eige Joint Compound	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622094.HPL Description: W	0703-MAE-113A /hite Drywall	Yes	ND	3 CE, 3 FG	94 %	B, G, M	AKB	7/15/2003
2622095.HPL Description: W	0703-MAE-113B /hite Drywall	Yes	ND	5 CE, 5 FG	90 %	B, G, M	AKB	7/15/2003
2622096.HPL Description: W	0703-MAE-113C /hite Drywall	Yes	ND	3 CE, 2 FG	95 %	B, G, M	AKB	7/15/2003
2622097.HPL Description: T	0703-MAE-114A an Ceiling Tile	Yes	ND	95 CE, 3 FG	2 %	M	AKB	7/15/2003
2622098.HPL Description: T	0703-MAE-114B an Ceiling Tile	Yes	ND	99 CE	1 %	М	AKB	7/15/2003
2622099.HPL Description: T	0703-MAE-114C an Ceiling Tile	Yes	ND	97 CE, 2 FG	1 %	М	AKB	7/15/2003

RJ Lee Group Job No:

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622100.HPL Description: Gr	0703-MAE-115A ay Cement Material	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622101.HPL Description: Gr	0703-MAE-115B ay Cement Material	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622102.HPL Description: Gr	0703-MAE-115C ay Cement Material	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622103.HPL Description: Be	0703-MAE-116A ige Joint Compound	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622104.HPL Description: Be	0703-MAE-116B lige Joint Compound	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622105.HPL Description: Be	0703-MAE-116C lige Joint Compound	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622106.HPL Description: Be	0703-MAE-117A lige Adhesive	Yes	ND	<1 CE	100 %	В, М	AKB	7/15/2003
2622107.HPL Description: Be	0703-MAE-117B sige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622108.HPL Description: Be	0703-MAE-117C ige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003

RJ Lee Group Job No: BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622109.HPL Description: B	0703-MAE-118A eige And Red Gasket	Yes	70 CH	-	30 %	В, М	AKB	7/15/2003
2622110.HPL Description: B	0703-MAE-118B eige And Red Gasket	Yes	70 CH	-	30 %	В, М	AKB	7/15/2003
2622111.HPL Description: B	0703-MAE-118C eige And Red Gasket	Yes	70 CH	-	30 %	В, М	AKB	7/15/2003
2622112.HPL Description: B	0703-MAE-119A eige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622113.HPL Description: B	0703-MAE-119B eige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622114.HPL Description: B	0703-MAE-119C eige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/15/2003
2622115.HPL Description: W	0703-MAE-120A /hite And Gray Woven N	Yes Material	50 CH	35 SF	15 %	В, М	AKB	7/15/2003
2622116.HPL Description: W	0703-MAE-120B /hite And Gray Woven N	Yes Material	50 CH	35 SF	15 %	В, М	AKB	7/15/2003
2622117.HPL Description: W	0703-MAE-120C /hite And Gray Woven N	Yes Material	50 CH	35 SF	15 %	В, М	AKB	7/15/2003

RJ Lee Group Job No:

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622118.HPL Description: B	0703-MAE-121A eige Fibrous Glass	Yes	ND	5 CE	95 %	В, М	AKB	7/16/2003
2622119.HPL Description: B	0703-MAE-121B eige Fibrous Glass	Yes	ND	5 CE, 90 FG	5 %	В, М	AKB	7/16/2003
2622120.HPL Description: B	0703-MAE-121C eige Fibrous Glass	Yes	ND	3 CE, 95 FG	2 %	В, М	AKB	7/16/2003
2622121.HPL Description: B	0703-MAE-122A lack Tar Material	Yes	ND	25 CE, 2 FG, 10 SF	63 %	Т, В, М	AKB	7/16/2003
2622122.HPL Description: B	0703-MAE-122B lack Tar Material	Yes	ND	20 CE, 2 FG, 15 SF	63 %	Т, В, М	AKB	7/16/2003
2622123.HPL Description: B	0703-MAE-122C lack Tar Material	Yes	ND	20 CE, 2 FG, 15 SF	63 %	Т, В, М	AKB	7/16/2003
2622124.HPL Description: Ta	0703-MAE-123A an Adhesive	Yes	ND	2 CE, 2 SF	96 %	В, М	AKB	7/16/2003
2622125.HPL Description: Ta	0703-MAE-123B an Adhesive	Yes	ND	2 CE, 2 SF	96 %	В, М	AKB	7/16/2003
2622126.HPL Description: Ta	0703-MAE-123C an Adhesive	Yes	ND	2 CE, 2 SF	96 %	В, М	AKB	7/16/2003

RJ Lee Group Job No: BA

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622127.HPL Description: Gr	0703-MAE-124A ay Glazing Material	Yes	ND	<1 CE	100 %	В, М	AKB	7/16/2003
2622128.HPL Description: Gr	0703-MAE-124B ray Glazing Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622129.HPL Description: Gr	0703-MAE-124C ay Glazing Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622130.HPL Description: Gr	0703-MAE-125A ay Debris Material	Yes	ND	<1 CE, <1 FG, <1 SF	100 %	B, OP, M	AKB	7/16/2003
2622131.HPL Description: Gr	0703-MAE-125B ay Debris Material	Yes	ND	<1 CE, <1 FG, <1 SF	100 %	B, OP, M	AKB	7/16/2003
2622132.HPL Description: Gr	0703-MAE-125C ray Debris Material	Yes	ND	<1 CE, <1 FG, <1 SF	100 %	В, М	AKB	7/16/2003
2622133.HPL Description: Be	0703-MAE-126A sige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622134.HPL Description: Be	0703-MAE-126B sige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622135.HPL Description: Be	0703-MAE-126C sige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/16/2003

RJ Lee Group Job No:

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622136.HPL Description: Bl	0703-MAE-127A lack Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622137.HPL Description: Bl	0703-MAE-127B lack Material	Yes	ND	<1 CE	100 %	В, М	AKB	7/16/2003
2622138.HPL Description: Bl	0703-MAE-127C lack Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622139.HPL Description: Be	0703-MAE-128A eige Gasket Material	Yes	70 CH	-	30 %	В, М	AKB	7/16/2003
2622140.HPL Description: Be	0703-MAE-128B eige Gasket Material	Yes	70 CH	-	30 %	В, М	AKB	7/16/2003
2622141.HPL Description: Be	0703-MAE-128C eige Gasket Material	Yes	65 CH	-	35 %	В, М	AKB	7/16/2003
2622142.HPL Description: Be	0703-MAE-129A eige Adhesive	Yes	ND	3 SF	97 %	В, М	AKB	7/16/2003
2622143.HPL Description: Bo	0703-MAE-129B eige Adhesive	Yes	ND	3 SF	97 %	В, М	AKB	7/16/2003
2622144.HPL Description: Bo	0703-MAE-129C eige Adhesive	Yes	ND	3 SF	97 %	В, М	AKB	7/16/2003

RJ Lee Group Job No:

BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622145.HPL Description: Gr	0703-MAE-130A ay Material	Yes	ND	<1 CE	100 %	В, М	AKB	7/16/2003
2622146.HPL Description: Gr	0703-MAE-130B ay Material	Yes	ND	<1 CE	100 %	В, М	AKB	7/16/2003
2622147.HPL Description: Gr	0703-MAE-130C ay Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622148.HPL Description: Be	0703-MAE-131A lige Adhesive	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622149.HPL Description: Be	0703-MAE-131B sige Adhesive	Yes	ND	<1 CE	100 %	В, М	AKB	7/16/2003
2622150.HPL Description: Be	0703-MAE-131C sige Adhesive	Yes	ND	<1 CE	100 %	В, М	AKB	7/16/2003
2622151.HPL Description: Gr	0703-MAE-132A ay Cement Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622152.HPL Description: Gr	0703-MAE-132B ay Cement Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003
2622153.HPL Description: Gr	0703-MAE-132C ay Cement Material	Yes	ND	-	100 %	В, М	AKB	7/16/2003

RJ Lee Group Job No: BAK307036

Client Job No:

101323 1.1/Mannheim E/S

RJLG Sample Number	Client Sample Number	Homogeneous	Asbestos Detected(%)	Non-Asbestos Fibers(%)	Non-Fibrous Materials(%)	Matrix Material	Analyst	Analysis Date
2622154.HPL Description: Bla	0703-MAE-133A ack Material	Yes	ND	3 CE	97 %	В, М	AKB	7/16/2003
2622155.HPL Description: Bla	0703-MAE-133B ack Material	Yes	ND	5 CE, <1 SF	95 %	В, М	AKB	7/16/2003
2622156.HPL Description: Bla	0703-MAE-133C ack Material	Yes	ND	3 CE	97 %	В, М	AKB	7/16/2003

RJ Lee Group Job No: BAK307036

Allan K. Bullock

Authorized Signature

Allan K. Bullock, Microscopist

#### ASBESTOS NON-ASBESTOS NON-FIBROUS MATERIALS

AM = Amosite	CE = Cellulose	AM = Amphibole	HY = Hydromagnesite	Q = Quartz
AC = Actinolite	MW = Mineral Wool	B = Binder	M = Miscellaneous	T = Tar
AN = Anthophyllite	FG = Fibrous Glass	CA = Carbonates	MI = Mica	V = Vermiculite
CH = Chrysotile	SF = Synthetic Fibers	CL = Clay	OP = Opaque	
CR = Crocidolite	H = Hair	F = Feldspar	OR = Organic	
TR = Tremolite	W = Wollastonite	G = Gypsum	P = Perlite	
	OF = Other Fibers			

#### DISCLAIMER NOTES

- "ND" indicates no asbestos was detected; the method detection limit is 1%.
- $\bullet \ "Trace" \ or \ "<1" \ indicates \ as bestos \ was \ identified \ in \ the \ sample, \ but \ the \ concentration \ is \ less \ than \ the \ method \ quantitation \ limit \ of \ 1\%.$
- PLM coefficients of variance range from approximately 1.8 at the quantitation limit of 1% to 0.1 at high fiber concentrations.
- Samples are archived for three months following analysis and are then properly discarded.
- These results are submitted pursuant to RJ Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which these results are used or interpreted.
- This test report relates to the items tested.
- This report is not valid unless it bears the name of a NVLAP-approved signatory.
- Any reproduction of this document must include the entire document in order for the report to be valid.
- This report may not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
- Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar nonfriable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as "non-asbestos-containing."

### DEPARTMENT OF DEFENSE EDUCATION ACTIVITY ASBESTOS MANAGEMENT PROGRAM

## 2003 Asbestos Management Plan

for

### Mannheim American Elementary School Mannheim-Kaefertal, Germany HE 3469

**Prepared For:** 

Department of Defense Education Activity
Logistics Division
4040 North Fairfax Drive
Arlington, Virginia 22203-1635

**Prepared By:** 

Baker Environmental, Inc. Airside Business Park 100 Airside Drive Moon Township, PA 15108



**Under Contract With:** 

U.S. Army Corps of Engineers Transatlantic Programs Center Winchester, Virginia

#### ASBESTOS MANAGEMENT PLAN FOR MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### **TABLE OF CONTENTS**

#### **IMPORTANT FOREWORD**

#### **SECTIONS**

1.0	INTRODUCTION
2.0	LOCAL EDUCATION AGENCY REPRESENTATIVE
3.0	ASBESTOS COORDINATOR (AC)
4.0	SUMMARY OF INSPECTION FINDINGS
5.0	RECOMMENDED MANAGEMENT ACTIONS
6.0	REMOVED ACM
7.0	PLANNED ACTIVITIES
8.0	NOTIFICATION OF EMPLOYEES AND BUILDING OCCUPANTS
9.0	EVALUATION OF RESOURCE REQUIREMENTS
10.0	MANDATORY RECORDS

#### **EXHIBIT**

8.1 Sample Notification Letter to Employees and Building Occupants

#### **TABLES**

- 4.1 ACM in Each Building
- 5.1 Recommended Management Actions for ACM
- 6.1 Listing of ACM
- 7.1 Area(s) Requiring Initial or Additional Cleaning

#### **TABLE OF CONTENTS (cont.)**

#### TABLES (cont.)

8.1 Notification Efforts Completed by Asbestos Coordinator 9.1 Recommended Inventory for Asbestos O&M Program Equipment 9.2 Estimated Resources for Recommended Management Actions 10.1 Air Sampling Record 10.2 **Training Record** 10.3 Periodic Surveillance Record 10.4 **Cleaning Activities** 10.5 Operations and Maintenance Activity Record 10.6 Major Asbestos Activities

#### **APPENDICES**

10.7

- A Management Planner Certificate
- B Copies of Asbestos-Related Activity Notification Documents
- C Air Samples Laboratory Analysis Reports

Fiber Release Episodes Record

- D Glossary
- E Abatement Item Listing
- F U.S. EPA Final Rule: Asbestos-Containing Materials in Schools

#### **IMPORTANT FOREWORD**

The information presented herein, together with historical records for this location, satisfies the reporting requirements of the AHERA legislation and DODEA policy regarding Asbestos Management Plans.

FOR A SUMMARY TABULATION OF WHERE ASBESTOS WAS FOUND, AND WHAT SHOULD BE DONE ABOUT IT, PLEASE REFER TO TABLE 5.1 PRINTED ON BLUE-TINTED PAPER.

Please also note that not all building materials have been tested. Examples of this may be materials which are hidden from view, inaccessible, or where sampling would be destructive. THEREFORE, THERE IS NO ASSURANCE THAT UNTESTED MATERIALS ARE ASBESTOS-FREE.

#### 1.0 INTRODUCTION

This Asbestos Management Plan for Mannheim American Elementary School is a result of the inspection conducted by Baker Environmental, Inc. (Baker). The Asbestos Management Plan should be used in combination with the 2003 AHERA Inspection Report and the Operations and Maintenance Manual.

This plan contains all of the elements described in the U.S. Environmental Protection Agency (EPA) Rule, "Asbestos-Containing Materials in Schools," 40 Code of Federal Regulations (CFR), Part 763. The EPA Rule was promulgated on October 30, 1987, as required by the Asbestos Hazard Emergency Response Act (AHERA) of 1986. This Asbestos Management Plan was developed by an EPA-accredited management planner and includes:

- A description of inspections and management actions;
- Recommendations;
- Names of accredited persons who performed required work; and
- A plan for inspection, periodic surveillance, and operations and maintenance.

Under AHERA, a Local Education Agency or "LEA" has numerous responsibilities. For the Department of Defense Dependents Schools (DODDS), the LEA is defined as "the governing authority of any school operated under the defense dependents' education system provided for under the Defense Dependents' Education Act of 1978." In accordance with DODEA's Asbestos Management Program Procedures (DS Manual 4800.3), the Asbestos Program Manager at DODEA headquarters will serve the function of the LEA. The LEA responsibilities include the following:

- Ensure that the activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with Subpart E of this part.
- Ensure that all custodial and maintenance employees are properly trained as required by Subpart E of AHERA (reference (b)) and other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration asbestos standard for construction, the EPA worker protection rule, or applicable State regulations).
- Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress.
- Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACM and suspected ACM assumed to be ACM.
- Ensure that warning labels are posted in accordance with Part 763.95 of AHERA (reference (b)).
- Ensure that management plans are available for inspection and notification of such availability has been provided as specified in the management plan in Part 763.93(g) of AHERA (reference (b)).
- Designate an Asbestos Coordinator (AC) to ensure that requirements of the LEA are
  properly implemented at the local level. Principals are hereby designated as the AC
  for their facilities. For non-school facilities, the AC shall be the Administrative
  Manager of the unit.

- Ensure that the AC and/or their designated person receives adequate training to perform duties assigned under this section. Such training shall provide, as necessary, basic knowledge of:
  - -- Health effects of asbestos.
  - -- Detection, identification, and assessment of ACM.
  - -- Options for controlling ACM.
  - -- Asbestos management programs.
  - -- Relevant Federal and State regulations concerning asbestos, including those in this Subpart E and those of the Occupational Safety and Health Administration, U.S. Department of Labor, the U.S. Department of Transportation and the U.S. Environmental Protection Agency.
- Ensure that the presence of ACM in a DODEA building is considered before initiating repair, maintenance, or construction projects.
- Provide timely notifications of fiber releases to all appropriate DODEA personnel,
   employee representative organizations, base command, and parents.

#### 2.0 LOCAL EDUCATION AGENCY REPRESENTATIVE

The LEA Representative designated by the Department of Defense Education Activity (DODEA) to ensure that the general LEA responsibilities described in Title 40 CFR, Part 763.84, are carried out is:

Ms. Liisa M. White Department of Defense Education Activity Logistics Division/Facilities Branch 4040 North Fairfax Drive Arlington, VA 22203-1635 (703) 696-3850 (ext. 1801) (703) 696-4030 (Fax)

This individual is qualified to perform the duties assigned to the LEA Representative as described in Title 40 CFR, Part 763.

#### **LEA Certification**

As the LEA Representative, I certify that responsibilities as stipulated by Title 40 CFR, Section 763.84, have been met or will be met to the extent feasible and in a manner consistent with national security.

Fin of White

Liisa M. White

#### 3.0 ASBESTOS COORDINATOR (AC)

The current Asbestos Coordinator (AC) designated to carry out the duties of the LEA at Mannheim American Elementary School is:

Ms. Bonnie Bowen-Hannan Mannheim American Elementary School Unit 29938 APO AE 09086

Telephone: 49-621-722109 Telefax: 49-621-723905

According to asbestos management program procedures described in DODEA's DS Manual 4800.3, Section D, Paragraph 3:

"The AC will assume the duties directly or may delegate the duties to a staff employee at the local level; however, the AC retains the responsibility and accountability for implementation of the asbestos program at the local level."

If the above named AC has delegated responsibilities, please insert information below:

Name	Signature	Timeframe

#### 4.0 SUMMARY OF INSPECTION FINDINGS

The 2003 AHERA Inspection (2003 inspection) of Mannheim American Elementary School was conducted on 2-8 July 2003. Table 4.1 following this page summarizes the findings concerning the presence of ACM in each building.

Detailed results of the 2003 inspection, sample locations, ACM condition assessments, sample analysis, and inspector accreditation credentials are included in the 2003 AHERA Inspection Report for Mannheim American Elementary School. A copy of this report was included with this Asbestos Management Plan when it was submitted to Ms. Bonnie Bowen-Hannan.

#### MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### **TABLE 4.1 - ACM IN EACH BUILDING**

BUILDING NUMBER	HOMO. MATERIAL NUMBER	MATERIAL TYPE (MATERIAL DESCRIPTION)	MATERIAL LOCATION(S)
0697 (Unknown)	001	VINYL FLOOR TILE (1' X 1' BEIGE WITH WHITE AND BLACK SPECKS)	03, 04A, 121C, 122C, 123C, 124C, 1250 128C, 129C, 221C, 222C, 223C, 224C, 228C, 229C, 231D, 232D, 233D, 234D, 238D, 239D
0697 (Unknown)	019	SHEET GASKET (2" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICA ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILEF ROOM
0697 (Unknown)	021	STALL PARTITIONS (GRAY CEMENT BOARD)	GIRLS TOILET G3, OLD BOILER ROOI 09D
0697 (Unknown)	036	FLOOR ADHESIVE (BLACK, UNDER 1' X 1' BEIGE WITH WHITE AND BLACK SPECKS VINYL FLOOR TILE)	03, 04A, 121C, 122C, 123C, 124C, 1250 128C, 129C, 221C, 222C, 223C, 224C, 228C, 229C, 231D, 232D, 233D, 234D, 238D, 239D
0697 (Unknown)	037	FLOOR ADHESIVE (BLACK, UNDER GREEN RAISED DOT RUBBER FLOOR SHEETING)	CORRIDOR E, CORRIDOR H, STAIRW 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29 30A, 31
0697 (Unknown)	039	WALL PLASTER (WHITE)	CORRIDOR F
0697 (Unknown)	041	FLOOR ADHESIVE (BROWN GLUE ON BLACK ADHESIVE, UNDER GREEN VINYL FLOOR SHEETING)	CORRIDOR B2
0697 (Unknown)	118	SHEET GASKET (4" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	09 LOBBY, 27B
0697 (Unknown)	120	ROPE GASKET (WHITE)	MECHANICAL ROOM 3A
0697K (Unknown)	128	SHEET GASKET (4" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	MR

#### 5.0 RECOMMENDED MANAGEMENT ACTIONS

#### 5.1 <u>Management Planner</u>

The recommended management actions for each ACM or assumed ACM are presented in Table 5.1. These recommendations were prepared by the Baker Management Planner identified below:

Jeffrey C. Kolish

The Management Planner became accredited by successfully completing an EPA-approved course developed under Section 206(c) of Title II of the Toxic Substances Control Act. A copy of the Management Planner's accreditation certificate is located in Appendix A.

Table 5.1 includes blank Begin Date and End Date columns. These columns were included to assist the AC in documenting implementation of recommended management actions. Upon satisfactory completion of each management action, the AC will record the date in the appropriate space on Table 5.1 and forward a copy of the page to the Area Office.

#### 5.2 Reasons for Selecting Management Actions

The rationale for selecting the management actions recommended in this report is based on guidelines presented in the EPA Rule "Asbestos-Containing Materials in Schools" and DODEA policy. The rationale is as follows:

Significantly damaged surfacing material and miscellaneous material is likely to release asbestos fibers into the air; therefore, these material(s) should be removed and replaced with material(s) that do not contain asbestos, or encapsulated or enclosed if such action would be feasible and sufficient to protect human health and the environment.

- Damaged surfacing material and miscellaneous material may release asbestos
  fibers into the air; therefore, the damaged areas should be immediately repaired. If
  repair of the damaged area(s) is not feasible, the material should be removed and
  replaced with a material that does not contain asbestos, or encapsulated or enclosed
  if such action would be feasible and sufficient to protect human health and the
  environment.
- Damaged or significantly damaged thermal system insulation may release asbestos
  fibers into the air; therefore, the damaged areas should be repaired to inhibit
  asbestos fiber release. After these repairs are completed, the insulation should be
  maintained in an intact state and undamaged condition or removed and replaced
  with a material that does not contain asbestos. If repair of the damaged areas is not
  feasible, the material should be removed.
- ACM with a potential for damage, including thermal system insulation, surfacing
  material, or miscellaneous material, may release asbestos fibers into the air if
  damaged; therefore, the material should be properly maintained in accordance with
  an operations and maintenance program or removed and replaced with a material
  that does not contain asbestos.
- ACM with a potential for significant damage, including thermal system insulation, surfacing material, or miscellaneous material, is likely to release asbestos fibers into the air if damaged significantly; therefore, preventive measures should be taken to ensure that the material will not become significantly damaged. An operations and maintenance program should be implemented, or the material should be enclosed or encapsulated or removed and replaced as soon as possible with a material that does not contain asbestos.
- Any ACM, regardless of condition, that may be disturbed by any planned action such
  as maintenance, installation, and construction, or any other modification to the
  building, must be removed prior to conducting the planned action.

#### MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS FOR ACM

BUILDING NUMBER	HOMO. MTRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	FRI- ABLE	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)	BEGIN DATE	END DATE
0697 (Unknown)	001	VINYL FLOOR TILE (1' X 1' BEIGE WITH WHITE AND BLACK SPECKS)	NO	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #036. THIS MATERIAL IS LOCATED BELOW EXISTING CARPET IN SOME LISTED LOCATIONS. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697 (Unknown)	019	SHEET GASKET (2" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	NO	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICAL ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILER ROOM		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697 (Unknown)	021	STALL PARTITIONS (GRAY CEMENT BOARD)	NO	GIRLS TOILET G3, OLD BOILER ROOM, 09D	ONE STALL PARTITION IN ROOM 09D IS DAMAGED AND NEEDS TO BE REMOVED. THERE IS ALSO ONE UNINSTALLED STALL PARTITION IN THE OLD BOILER ROOM THAT NEEDS TO BE REMOVED.	1. PORTIONS OF THIS MATERIAL SHOULD BE REMOVED WITHIN ONE YEAR OF RECEIPT OF THIS REPORT.  2. THIS MATERIAL COULD BE REMOVED BY QUALIFIED MAINTENANCE PERSONNEL WHO HAVE RECEIVED TRAINING IN SMALL SCALE, SHORT DURATION ABATEMENT PROJECTS.  3. FOR THE REMAINDER OF THIS MATERIAL, NO IMMEDIATE ABATEMENT IS REQUIRED.  4. CONSULT THE O & M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THE REMAINDER OF THIS MATERIAL.  5. CONTINUE SURVEILLANCE OF THE REMAINDER OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.		
0697 (Unknown)	036	FLOOR ADHESIVE (BLACK, UNDER 1' X 1' BEIGE WITH WHITE AND BLACK SPECKS VINYL FLOOR TILE)	NO	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	THIS IS THE ADHESIVE FOR MATERIAL #001. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697 (Unknown)	037	FLOOR ADHESIVE (BLACK, UNDER GREEN RAISED DOT RUBBER FLOOR SHEETING)	NO	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	THIS IS THE ADHESIVE FOR MATERIAL #005.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		

#### MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS FOR ACM

BUILDING NUMBER	HOMO. MTRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	FRI- ABLE	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)	BEGIN DATE	END DATE
0697 (Unknown)	039	WALL PLASTER (WHITE)	NO	CORRIDOR F		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697 (Unknown)	041	FLOOR ADHESIVE (BROWN GLUE ON BLACK ADHESIVE, UNDER GREEN VINYL FLOOR SHEETING)	NO	CORRIDOR B2	AT THE TIME OF THE 1997, 2000, AND 2003 AHERA INSPECTIONS, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED DUE TO THE APPLICATION OF A NEW CONCRETE FLOORING PRODUCT. IT WAS ASSUMED THAT THIS MATERIAL STILL REMAINS WITHIN THE BUILDING.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697 (Unknown)	118	SHEET GASKET (4" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	NO	09 LOBBY, 27B	THIS MATERIAL IS LOCATED WITHIN THE PIPE CHASE INSIDE 09 LOBBY.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697 (Unknown)	120	ROPE GASKET (WHITE)	NO	MECHANICAL ROOM 3A	THIS MATERIAL IS LOCATED ON PIPING AND IS USED AS A SPACER FOR CLAMPS.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		
0697K (Unknown)	128	SHEET GASKET (4" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	NO	MR		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>		

#### 6.0 REMOVED ACM

When removal management actions have been initiated, the AC should provide a written account of any identified ACM that has been removed from the location. This written account must be updated as removal management actions are completed. Table 6.1 lists the ACM determined to be remaining at Mannheim American Elementary School at the completion of the 2003 inspection. The AC should update Table 6.1 each time a removal management action is completed by documenting the date the action was completed. A copy of the updated Table 6.1 should be forwarded to the Area Office.

# MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### **TABLE 6.1 - LISTING OF ACM**

BUILDING NUMBER	HOMO. MTRL. NO.	MATERIAL TYPE	MATERIAL LOCATION(S)	MATER QUANT	
0697 (Unknown)	001	VINYL FLOOR TILE	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	18,663	SF
0697 (Unknown)	019	SHEET GASKET	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICAL ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILER ROOM	222	EA
0697 (Unknown)	021	STALL PARTITIONS	GIRLS TOILET G3, OLD BOILER ROOM, 09D	220	SF
0697 (Unknown)	036	FLOOR ADHESIVE	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	18,663	SF
0697 (Unknown)	037	FLOOR ADHESIVE	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	7,426	SF
0697 (Unknown)	039	WALL PLASTER	CORRIDOR F	250	SF
0697 (Unknown)	041	FLOOR ADHESIVE	CORRIDOR B2	4,576	SF
0697 (Unknown)	118	SHEET GASKET	09 LOBBY, 27B	18	EA
0697 (Unknown)	120	ROPE GASKET	MECHANICAL ROOM 3A	1	EA
0697K (Unknown)	128	SHEET GASKET	MR	4	EA

#### 7.0 PLANNED ACTIVITIES

#### 7.1 Plan for Reinspection

Within three years of the effective date of this Asbestos Management Plan and triennially thereafter, all known or assumed ACM <u>remaining</u> in each building still used by DODDS should be reinspected by an accredited inspector. The purpose of the reinspection is to reassess any ACM remaining in each building. The reinspection will be performed in accordance with Title 40 CFR, Section 763.85(b), and a record of the reinspection will be incorporated into the Asbestos Management Plan within 90 days of the reinspection and will contain the following information:

- Date of the reinspection
- Changes in the condition of known or assumed ACM
- Locations where samples were collected
- Assessments or reassessments of friable ACM
- Signature(s) and certification(s) of inspector(s)

#### 7.2 Plan for Operations and Maintenance

The Operations and Maintenance (O&M) Program has been developed for Mannheim American Elementary School for implementation by building maintenance and custodial staff. The O&M Program is described in detail in the O&M Manual. A copy of the O&M Manual was attached to this Asbestos Management Plan when it was transmitted to Ms. Bonnie Bowen-Hannan. The O&M Program includes:

- Procedures for initial and additional cleaning of areas where friable ACM is located.
- Procedures to protect building occupants during operations and maintenance activities disturbing friable and nonfriable ACM.
- Procedures to follow if friable ACM is dislodged and fibers are released.

#### 7.3 Plan for Periodic Surveillance

Within six months of the effective date of this Asbestos Management Plan, and at least once every six months thereafter, a qualified person will visually inspect all identified known or assumed ACM. Periodic surveillance involves a visual inspection to note changes in condition. A record of the surveillance, including the date and any changes in the condition of materials, will be maintained by the AC and submitted to the Area Office. The periodic surveillance records are located in Section 10, Table 10.3, of this Asbestos Management Plan.

#### 7.4 Recommendations for Initial and Additional Cleaning

The following initial and additional cleaning practices should be instituted:

- <u>Initial cleaning</u>. Unless the building has been cleaned using equivalent methods within the previous six months, all areas of a school building where friable ACM, damaged or significantly damaged thermal system insulation ACM, or friable assumed ACM are present shall be cleaned before the initiation of any management action, other than O&M activities or repair, according to the following procedures:
  - High efficiency particulate air (HEPA)-vacuum and steam-clean all carpets.
  - HEPA-vacuum or wet-clean all other floors and all other horizontal surfaces.
  - Dispose of all debris, filters, mopheads, and cloths in sealed, leakproof containers.
- Additional cleaning. Unless initial cleaning has been accomplished within the previous six months, all areas of a building where friable damaged or significantly damaged ACM, damaged or significantly damaged asbestos-containing thermal system insulation, or friable damaged or significantly damaged assumed ACM are present, shall be cleaned. Cleaning methods used shall be equivalent to initial cleaning practices.

Table 7.1 identifies the areas requiring initial or additional cleaning as described in the O&M Manual.

# Mannheim American Elementary School HE 3469

Table 7.1 Area(s) Requiring Initial or Additional Cleaning

THERE ARE NO AREAS WHICH REQUIRE INITIAL OR ADDITIONAL CLEANING IN THIS FACILITY

#### 8.0 NOTIFICATION OF EMPLOYEES AND BUILDING OCCUPANTS

Information concerning inspections, reinspections, management actions, and post management action activities (e.g., surveillance activities) must be provided to employees and building occupants (or their legal guardians) on an annual basis. Exhibit 8.1 is a sample notification letter. The AC must maintain a record of all notification efforts that have been undertaken. The notification record is contained in Table 8.1. The AC must update this record after each annual notification. Copies of notification letters and any additional public information issued by the AC will be inserted into Appendix B of this Asbestos Management Plan. The AC will forward copies of the documents to the Area Office.

#### **EXHIBIT 8.1**

#### SAMPLE NOTICE FOR AHERA INSPECTION OR REINSPECTION

(Letterhead) (Date)

#### MEMORANDUM FOR PARENTS AND STAFF

SUBJECT: Notification of AHERA inspection (or reinspection)

As required by the Asbestos Hazard Emergency Response Act (AHERA) of 1986, our buildings have been inspected or reinspected for asbestos-containing materials (ACM). The most recent inspection was conducted on **[take date from most recent Asbestos Management Report]** in accordance with Environmental Protection Agency (EPA) regulations and DoDEA policy.

The results of the inspection or reinspection indicate we have the following asbestos materials in our building(s): [refer to table 6.1 of the Asbestos Management Plan addendum]

## THE FOLLOWING ITALICIZED TEXT IS AN EXAMPLE OF HOW TO PRESENT THE INFORMATION:

- vinyl floor tiles in the administrative offices, teachers' lounge, and first floor classrooms and hallways of Bldg 2001,
  - insulation on steam pipes in the boiler room of Bldg 2002,
  - cement roof panels on the walkway between Bldgs 2001 and 2002.

The insulation on the steam pipes has been recommended for removal. Project specifications are being prepared and the project is expected to be completed during the summer recess.

The cement roof panels were removed during the exterior renovations over the summer recess this year. The inspectors found the vinyl floor tiles to be in good condition and indicated that there is no reason to remove them at this time.

As required by EPA, a periodic surveillance program is in effect for asbestos materials that remain in place and their condition will be closely monitored.

A copy of the Asbestos Management Plan is kept in our office and is available for your review. If you have any questions or concerns, please do not hesitate to contact me.

John Q. Smith Principal

# Mannheim American Elementary School HE 3469

Table 8.1

Notification Efforts Completed by Asbestos Coordinator

Date	Activity	Notification To	Notification By	Comments

#### 9.0 EVALUATION OF RESOURCE REQUIREMENTS

#### 9.1 <u>O&M Program Supplies</u>

The cleaning and preventive measures specified in this Asbestos Management Plan require the availability of disposable and non-disposable items. Table 9.1 lists the recommended equipment inventory required for use in asbestos management activities. This equipment must be available for use by properly trained maintenance and custodial staff.

Table 9.1

Recommended Inventory for

Asbestos O&M Program Equipment

Item	Quantity	Unit Cost	Total Estimated Cost
"Danger Asbestos" Labeled Bags 75/Roll	1	\$52.00/Roll	\$52.00
6 mil Polyethylene Sheeting 10' X 100' Roll	1	\$29.00/Roll	\$29.00
Bridging Encapsulant 5 Gal Container	1	\$188.00/Container	\$188.00
Duct Tape 10/Box	1	\$55.00/Box	\$55.00
Garden Sprayer	1	\$30.00/Sprayer	\$30.00
Half Face Respirators	2	\$23.00/Respirator	\$46.00
HEPA Filter Vacuum	1	\$1,030.00/Vacuum	\$1,030.00
P100 Respirator Cartridges 10/Box	1	\$42.00/Box	\$42.00
Signs and Placards	1	\$60.00/Set	\$60.00
Tyvek Suits 25/Box	1	\$110.00/Box	\$110.00

#### 9.2 Resource Requirements for Management Actions

Table 9.2 defines the estimated resources required to carry out the recommended management actions for all homogeneous areas found to contain ACM.

To assist in understanding the information provided in Table 9.2, a description of each column heading is included below.

**BUILDING NUMBER** - Identifies each building included in the report. If the date of construction was known, this information is presented in parenthesis after the building number.

**HOMO. MATRL. NO. (Homogeneous Material Number)** - Numerical designation assigned to each homogeneous material (material that is uniform in color and texture, serves the same function, and was installed at the same time) encountered in a building.

**MATERIAL TYPE** - Brief description of the material, followed by information on distinguishing characteristics which may include function, size, color, shape, etc., if necessary.

**MATERIAL LOCATION(S)** - Short description detailing the specific location of the homogeneous material area.

**ABATEMENT ITEM** - Numerical designation assigned to each item required to carry out the management action. Appendix E contains an Abatement Item Listing providing a detailed description of each abatement item.

**UNIT COST** - Estimated unit cost associated with each abatement item. Appendix E contains an Abatement Item Listing providing an estimated unit cost for each abatement item.

**ESTIMATED QUANTITY** - Estimated quantity of the abatement item required to perform the task.

**ITEM COST** - Management action cost obtained by multiplying UNIT COST by ESTIMATED QUANTITY.

**ESTIMATED MATERIAL COST** - Estimated total cost for each asbestos material obtained by adding all ITEM COSTS for each material.

#### MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### TABLE 9.2 - ESTIMATED RESOURCES FOR RECOMMENDED MANAGEMENT ACTIONS

BUILDING NUMBER	HOMO. MATERIAL NUMBER	MATERIAL TYPE	MATERIAL LOCATION(S)	ABATEMENT ITEM	UNIT COST	ESTIMATED QUANTITY	ITEM COST	ESTIMATED MATERIAL COST
0697 (Unknown)	001	VINYL FLOOR TILE	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	200	\$67.50	24.00 HRS	\$1,620.00	\$1,620.00
0697 (Unknown)	019	SHEET GASKET	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICAL ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILER ROOM	200	\$67.50	3.00 HRS	\$202.50	\$202.50
0697	021	STALL PARTITIONS	GIRLS TOILET G3, OLD BOILER	54	\$27.94	2.00 SF	\$55.88	
(Unknown)			ROOM, 09D	200	\$67.50	3.00 HRS	\$202.50	\$258.38
0697 (Unknown)	036	FLOOR ADHESIVE	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	200	\$67.50	24.00 HRS	\$1,620.00	\$1,620.00
0697 (Unknown)	037	FLOOR ADHESIVE	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	200	\$67.50	24.00 HRS	\$1,620.00	\$1,620.00
0697 (Unknown)	039	WALL PLASTER	CORRIDOR F	200	\$67.50	1.50 HRS	\$101.25	\$101.25
0697 (Unknown)	041	FLOOR ADHESIVE	CORRIDOR B2	200	\$67.50	18.00 HRS	\$1,215.00	\$1,215.00
0697 (Unknown)	118	SHEET GASKET	09 LOBBY, 27B	200	\$67.50	1.50 HRS	\$101.25	\$101.25
0697 (Unknown)	120	ROPE GASKET	MECHANICAL ROOM 3A	200	\$67.50	1.50 HRS	\$101.25	\$101.25
0697K (Unknown)	128	SHEET GASKET	MR	200	\$67.50	1.50 HRS	\$101.25	\$101.25

#### MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

#### TABLE 9.2 - ESTIMATED RESOURCES FOR RECOMMENDED MANAGEMENT ACTIONS

BUILDING NUMBER	HOMO. MATERIAL NUMBER	MATERIAL TYPE	MATERIAL LOCATION(S)	ABATEMENT ITEM	UNIT COST	ESTIMATED QUANTITY	ITEM COST	ESTIMATED MATERIAL COST
--------------------	-----------------------------	---------------	----------------------	-------------------	--------------	-----------------------	-----------	-------------------------------

TOTAL COST \$6,941.00

#### 10.0 MANDATORY RECORDS

The EPA rule, "Asbestos-Containing Materials in Schools", Title 40 CFR, Part 763, requires that certain records be maintained in the administrative offices of the school and the LEA as part of the Asbestos Management Plan. For each area where ACM has been removed, the LEA will retain the required records for 3 years beyond the next reinspection. When records are updated, the AC will forward a copy of the updated record to the Area Office.

#### 10.1 Preventive Measures and Management Actions

The AC will maintain the required records by entering the appropriate information on Table 5.1 in Section 5.0 of this Asbestos Management Plan. Table 5.1 will be updated as the preventive measures management actions are completed.

Records of any air monitoring conducted in conjunction with the asbestos management program are documented on Table 10.1. Appendix C of this Asbestos Management Plan is reserved for copies of the laboratory analysis reports of any air samples collected.

#### 10.2 Training

A complete record of employee training is to be maintained on Table 10.2. As training is completed, the AC will record the appropriate information on Table 10.2.

#### 10.3 Periodic Surveillance

Each time periodic surveillance as defined under Title 40 CFR, Section 763.92(b), is performed, the AC will record in the appropriate spaces on Table 10.3 the name of the individual(s) conducting the surveillance activity, the location and date of the surveillance activity, and changes in the condition of the materials.

#### 10.4 Cleaning

Each time cleaning activities as described under Title 40 CFR, Section 763.91(c), are performed, the AC will record in the appropriate spaces on Table 10.4, the material and cleaning methods used, the date of the cleaning, the locations cleaned, and the name of the individual(s) performing the cleaning.

#### 10.5 Operations and Maintenance

Each time operations and maintenance activities involving ACM as defined under Title 40 CFR, Section 763.91(d), are performed in this school, the AC will record on Table 10.5 the name of the individual(s) performing the activity, the start and completion dates of the activity, the location where the activity occurred, a description of the activity, including preventive measures used, and, if ACM is removed, the name and location of the storage or disposal site of the ACM.

#### 10.6 Major Asbestos Activity

Each time a major asbestos activity as defined under Title CFR, Section 763.91(e), is performed, the AC will record on Table 10.6 the name and signature, the State of accreditation, and, if applicable, the accreditation number of the individual(s) performing the activity, the start and completion dates, the location where the activity occurred, a description of the activity including preventive measures used, and, if ACM is removed, the name and location of the storage or disposal site of the ACM.

#### 10.7 Fiber Release Episodes

For each asbestos fiber release episode as defined under Title 40 CFR, Section 763.91(f), the AC will record on Table 10.7 the date and location of the episode, the severity of release, the preventive measures or management actions taken, the name of the individual(s) performing the work, and the name and location of the storage or disposal site of any ACM removed.

#### **TABLE 10.1 AIR SAMPLING RECORD**

#### **TABLE 10.2 TRAINING RECORD**

SCHOOL TO INSERT TRAINING RECORDS

#### **TABLE 10.3 PERIODIC SURVEILLANCE RECORD**

Material	Surveillance Date	Location	Previous Condition	Current Condition	Name of Inspector

#### **TABLE 10.4 CLEANING ACTIVITIES**

Material	Cleaning Date	Location Cleaned	Individual Performing Cleaning

#### **TABLE 10.5 OPERATIONS AND MAINTENANCE ACTIVITY RECORD**

Name of Person Conducting the Activity	Start Date	Completion Date	Activity Location	Activity Description	Storage or Disposal Site for ACM

### **TABLE 10.6 MAJOR ASBESTOS ACTIVITIES**

Name and Signature	State of Accreditation	Start Date	Completion Date	Activity Location	Activity Description	Storage or Disposal Site for ACM

### TABLE 10.7 FIBER RELEASE EPISODES RECORD

Location	Date	Major or Minor Release	Management Action or Preventive Measures	Individuals Performing Work	Storage or Disposal Site for ACM

### **APPENDIX A**

### MANAGEMENT PLANNER CERTIFICATE



### **APPENDIX B**

# COPIES OF ASBESTOS-RELATED ACTIVITY NOTIFICATION DOCUMENTS

### **APPENDIX C**

### **AIR SAMPLES - LABORATORY ANALYSIS REPORTS**

**APPENDIX D** 

**GLOSSARY** 

### **GLOSSARY**

#### Abatement

Procedures which are implemented to remove asbestos materials from a damaged area, functional space, or a homogeneous area.

### **Asbestos**

A group of naturally occurring minerals that can be separated into fibers which are flexible, heat resistant and chemically inert. The following asbestos minerals are used commercially: Actinolite, Amosite, Anthophyllite, Chrysotile, Crocidolite, and Tremolite.

### Asbestos-Containing Material (ACM)

Per EPA regulations, any material that contains more than 1.0 percent asbestos by weight.

### **Asbestos Coordinator (AC)**

The person at the local level who serves as a focal point or liaison for asbestos activities. Per DODEA Asbestos Management Policy, this person is the Principal of a school, or District Superintendent at a DSO.

# Asbestos Hazard Emergency Response Act (AHERA)

An Act passed by Congress and signed by the President in October 1986 which requires the EPA to promulgate regulations requiring inspections for ACM, development of asbestos management plans, and management actions with respect to friable ACM in U.S. schools including DODDS.

# Asbestos Management Plan

Required by AHERA, a plan detailing the steps taken to control potential asbestos hazards in school buildings. **Asbestos Management** 

**Program** 

A program instituted by DODEA to comply with AHERA and to administer long-term control and surveillance of all ACM in school buildings.

**Containment System** 

A separation or barrier system that prevents the movement of asbestos-contaminated air from the abatement work area into uncontaminated areas.

**Encapsulation** 

The treatment of ACM with a penetrating or surface sealant in order to minimize the potential for asbestos fiber release.

**Enclosure** 

The system of containment that creates an airtight seal or barrier between the ACM and the adjacent space.

**EPA** 

**Environmental Protection Agency** 

**Friable** 

Any material which, when dry, may be crumbled, pulverized, or reduced to powder by hand pressure.

Homogeneous Sampling

Area

An area of surfacing material, thermal system insulation material, or miscellaneous material that is uniform in color or texture, serves the same function, and was installed at the same time.

Removal

The removal of ACM from any surface or component in all or a portion of a building.

Operations and
Maintenance (O&M)
Program

A program specifically designed to clean up asbestos fibers previously released, to prevent the release of fibers by minimizing ACM disturbance or damage, and to monitor the condition of the ACM.

### Surveillance

Periodic reinspection of friable and non-friable ACM on a frequency consistent with the requirements of the AHERA regulations.

### **APPENDIX E**

### ABBREVIATIONS USED ON THE ABATEMENT ITEM LISTING:

EA -- EACH

LF -- LINEAR FOOT

LS -- LUMP SUM

MH -- MAN HOUR

SF -- SQUARE FOOT

H -- HOUR

PR -- PAIR

Item	7.57.12.III.2.III. 2.101.III.0		
<u>Number</u>	Item Description	<u>Unit</u>	Unit Price
01	Removal and disposal of asbestos-containing vinyl floor tile. Removal by full containment method.	SF	\$26.50
02	Removal and disposal of asbestos-containing vinyl floor sheeting. Removal by full containment method.	SF	\$27.22
03	Removal and disposal of asbestos-containing floor adhesive. Removal by full containment method.	SF	\$26.50
04	Removal and disposal of asbestos-containing cement flooring. Removal by full containment method.	SF	\$33.70
05	Removal and disposal of asbestos-containing subfloor material. Removal by full containment method.	SF	\$32.98
06	Removal and disposal of asbestos-containing cove base adhesive. Removal by full containment method.	SF	\$26.50
07	Removal and disposal of asbestos-containing cove base. Removal by full containment method.	SF	\$26.50
10	Removal and disposal of asbestos-containing wall plaster. Removal by full containment method.	SF	\$30.10
11	Removal and disposal of asbestos-containing wallboard. Removal by full containment method.	SF	\$27.94
12	Removal and disposal of asbestos-containing cement wall panels. Removal by full containment method.	SF	\$28.66
13	Removal and disposal of asbestos-containing acoustical wall panels. Removal by full containment method.	SF	\$29.38
14	Removal and disposal of asbestos-containing fabric wall covering. Removal by full containment method.	SF	\$30.10
15	Removal and disposal of asbestos-containing paint. Removal by full containment method.	SF	\$30.10
16	Removal and disposal of asbestos-containing joint compound. Removal by full containment method.	SF	\$29.38

14	ADATEMENT ITEM LISTING		
Item <u>Number</u>	Item Description	<u>Unit</u>	Unit Price
17	Removal and disposal of asbestos-containing caulk. Removal by full containment method.	LF	\$31.90
18	Removal and disposal of asbestos-containing wall insulation. Removal by full containment method.	SF	\$27.58
19	Removal and disposal of asbestos-containing fireproofing. Removal by full containment method.	SF	\$31.18
20	Removal and disposal of asbestos-containing ceiling plaster. Removal by full containment method.	SF	\$30.82
21	Removal and disposal of asbestos-containing ceiling board. Removal by full containment method.	SF	\$30.82
22	Removal and disposal of asbestos-containing cement ceiling panels. Removal by full containment method.	SF	\$30.10
23	Removal and disposal of asbestos-containing ceiling tiles. Removal by full containment method.	SF	\$29.38
24	Removal and disposal of asbestos-containing ceiling insulation. Removal by full containment method.	SF	\$27.22
25	Removal and disposal of asbestos-containing ceiling rough finish. Removal by full containment method.	SF	\$31.54
26	Removal and disposal of asbestos-containing wall and ceiling plaster. Removal by full containment method.	SF	\$30.82
27	Removal and disposal of asbestos-containing cement wall and ceiling panels. Removal by full containment method.	SF	\$28.66
28	Removal and disposal of asbestos-containing wall and ceiling board. Removal by full containment method.	SF	\$29.02
29	Removal and disposal of asbestos-containing cement wall and ceiling tile. Removal by full containment method.	SF	\$30.10
30	Removal and disposal of asbestos-containing thermal pipe insulation. Removal by full containment method.	LF	\$36.58

ltom	/(D/(12))		
Item <u>Number</u>	Item Description	<u>Unit</u>	Unit Price
31	Removal and disposal of asbestos-containing thermal fitting insulation. Removal by full containment method.	EA	\$50.98
32	Removal and disposal of asbestos-containing thermal tape. Removal by full containment method.	LF	\$30.82
33	Removal and disposal of asbestos-containing cement pipe. Removal by full containment method.	LF	\$33.70
34	Removal and disposal of asbestos-containing sheet gasket. Removal by full containment method.	SF	\$29.38
35	Removal and disposal of asbestos-containing rope gasket. Removal by full containment method.	SF	\$35.14
36	Removal and disposal of asbestos-containing flex connector. Removal by full containment method.	EA	\$50.98
37	Removal and disposal of asbestos-containing duct insulation. Removal by full containment method.	SF	\$27.94
38	Removal and disposal of asbestos-containing cement duct. Removal by full containment method.	LF	\$31.54
39	Removal and disposal of asbestos-containing fire dampers. Removal method is to remove the entire fire damper intact.	EA	\$35.86
40	Removal and disposal of asbestos-containing internal boiler insulation. Removal by full containment method.	SF	\$36.58
41	Removal and disposal of asbestos-containing external boiler insulation. Removal by full containment method.	SF	\$29.38
42	Removal and disposal of asbestos-containing tank insulation. Removal by full containment method.	SF	\$27.94
43	Removal and disposal of asbestos-containing breeching/stack insulation. Removal by full containment method.	SF	\$29.38

14	ADATEMENT ITEM LISTING		
Item <u>Number</u>	Item Description	<u>Unit</u>	Unit Price
44	Removal and disposal of asbestos-containing thermal pipe and fitting insulation. Removal by full containment method.	LF	\$30.82
45	Removal and disposal of asbestos-containing mechanical equipment insulation. Removal by full containment method.	SF	\$29.38
46	Removal and disposal of asbestos-containing electrical wire insulation. Removal by full containment method.	LF	\$27.94
47	Removal and disposal of asbestos-containing lamp reflectors. Removal method is to remove the lamp intact.	EA	\$25.78
50	Removal and disposal of asbestos-containing dust/debris. Removal by full containment method.	SF	\$33.70
51	Removal and disposal of asbestos-containing kiln insulation. Removal by full containment method.	SF	\$35.14
52	Removal and disposal of asbestos-containing fire door lining. Removal method is to remove the fire door intact.	EA	\$36.58
53	Removal and disposal of asbestos-containing stage curtains. Removal by full containment method.	SF	\$27.22
54	Removal and disposal of asbestos-containing stall partitions. Removal by full containment method.	SF	\$27.94
55	Removal and disposal of asbestos-containing splash panels. Removal by full containment method.	SF	\$27.58
56	Removal and disposal of asbestos-containing windowsills. Removal by full containment method.	SF	\$32.26
57	Removal and disposal of asbestos-containing laboratory fume hoods. Removal by full containment method.	SF	\$29.38
58	Removal and disposal of asbestos-containing gloves.	PR	\$22.18
59	Removal and disposal of asbestos-containing fire blankets.	EA	\$26.50

Item	ASATEMENT TEM EIGTING		
<u>Number</u>	Item Description	<u>Unit</u>	<u>Unit Price</u>
60	Removal and disposal of asbestos-containing heat shields. Removal by full containment method.	SF	\$26.86
61	Removal and disposal of asbestos-containing napkin incinerator lining. Removal method is to remove the napkin incinerator intact.	EA	\$35.14
62	Removal and disposal of asbestos-containing chalkboards. Removal by partial containment method.	SF	\$27.22
63	Removal and disposal of asbestos-containing tabletops. Removal by partial containment method.	SF	\$27.22
64	Removal and disposal of asbestos-containing sink coating.	EA	\$30.10
65	Removal and disposal of asbestos-containing burner pad.	EA	\$22.18
66	Removal and disposal of asbestos-containing elevator brake shoes.	EA	\$35.14
67	Removal and disposal of asbestos-containing lab oven insulation. Removal by full containment method.	SF	\$32.98
68	Removal and disposal of asbestos-containing safe, cabinet, desk insulation. Removal by full containment method.	SF	\$500.00
70	Removal and disposal of asbestos-containing exterior soils. Removal by modified containment method.	SF	\$30.82
71	Removal and disposal of asbestos-containing exterior siding. Removal by modified containment method.	SF	\$29.38
72	Removal and disposal of asbestos-containing exterior siding shingles. Removal by modified containment method.	SF	\$29.02
73	Removal and disposal of asbestos-containing soffits. Removal by modified containment method.	SF	\$28.66
74	Removal and disposal of asbestos-containing facia. Removal by modified containment method.	SF	\$29.38

140.00	ADATEMENT ITEM LISTING		
Item <u>Number</u>	Item Description	<u>Unit</u>	Unit Price
75	Removal and disposal of asbestos-containing exterior plasters. Removal by modified containment method.	SF	\$35.14
76	Removal and disposal of asbestos-containing walkway ceiling. Removal by modified containment method.	SF	\$28.66
77	Removal and disposal of asbestos-containing cement roofing panels. Removal by modified containment method.	SF	\$29.38
78	Removal and disposal of asbestos-containing asphaltic roofing materials. Removal by modified containment method.	SF	\$30.10
79	Removal and disposal of asbestos-containing exterior caulks. Removal by modified containment method.	SF	\$32.26
80	Removal and disposal of asbestos-containing louvers. Removal by modified containment method.	SF	\$29.38
81	Removal and disposal of asbestos-containing cement corrugated roof. Removal by modified containment method.	SF	\$28.66
82	Removal and disposal of asbestos-containing asphaltic vapor barrier. Removal by modified containment method.	SF	\$29.02
83	Removal and disposal of asbestos-containing chimney lining. Removal by full containment method.	SF	\$36.58
84	Removal and disposal of asbestos-containing coal composition ceiling. Removal by full containment method.	SF	\$31.18
85	Removal and disposal of asbestos-containing ceiling tile adhesive. Removal by full containment method.	SF	\$29.38
86	Removal and disposal of asbestos-containing carpet. Removal by full containment method.	SF	\$26.50
87	Removal and disposal of asbestos-containing cement wall. Removal by full containment method.	SF	\$28.66

Item	ADATEMENT ITEM EIGTING		
Numb	per Item Description	<u>Unit</u>	Unit Price
88	Removal and disposal of asbestos-containing wall tile adhesive. Removal by full containment method.	SF	\$29.38
89	Removal and disposal of asbestos-containing wall tile. Removal by full containment method.	SF	\$29.38
90	Removal and disposal of asbestos-containing wall and ceiling tile. Removal by full containment method.	SF	\$29.38
91	Removal and disposal of asbestos-containing wall and ceiling tile adhesive. Removal by full containment method.	SF	\$29.38
92	Removal and disposal of other asbestos-containing thermal system insulation. Removal by full containment method.	LF	\$36.58
93	Removal and disposal of other asbestos-containing surfacing material. Removal by full containment method.	SF	\$30.82
94	Removal and disposal of other asbestos-containing miscellaneous material. Removal by full containment method.	SF	\$26.50
100	Conduct repair activities for an asbestos-containing material. Repair activities could include small-scale removal, small-scale encapsulation, small-scale enclosure, and/or repair of damaged areas. Hourly rate includes a 2-person, fully equipped crew to conduct repair activities.	HR	\$129.15
200	Conduct periodic surveillance of the asbestos-containing material. Periodic surveillance is anticipated to be conducted semiannually for 3 years.	МН	\$67.50
201	Institute an operations and maintenance program. Start- up costs include HEPA vacuum, glove bags, plastic, disposal, etc.	LS	\$4,050.00
202	Restock an existing operations and maintenance program to replace depleted supplies.	LS	\$1,080.00

### **APPENDIX F**

# U.S. EPA FINAL RULE: ASBESTOS-CONTAINING MATERIALS IN SCHOOLS

INSERT INFORMATION FROM ORIGINAL ASBESTOS MANAGEMENT PLAN

### DEPARTMENT OF DEFENSE EDUCATION ACTIVITY ASBESTOS MANAGEMENT PROGRAM

# 2003 Operations and Maintenance Manual

for

### Mannheim American Elementary School Mannheim-Kaefertal, Germany HE 3469

**Prepared For:** 

Department of Defense Education Activity
Logistics Division
4040 North Fairfax Drive
Arlington, Virginia 22203-1635

**Prepared By:** 

Baker Environmental, Inc. Airside Business Park 100 Airside Drive Moon Township, PA 15108



**Under Contract With:** 

U.S. Army Corps of Engineers Transatlantic Programs Center Winchester, Virginia

### OPERATIONS AND MAINTENANCE MANUAL FOR MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

### **TABLE OF CONTENTS**

### **IMPORTANT FOREWORD**

### **SECTIONS**

- 1.0 INTRODUCTION
- 2.0 BACKGROUND: ASBESTOS CHARACTERISTICS AND HEALTH EFFECTS
- 3.0 OPERATIONS AND MAINTENANCE PROGRAM ELEMENTS
- 4.0 EQUIPMENT REQUIREMENTS
- 5.0 RECOMMENDED MANAGEMENT ACTIONS FOR ASBESTOS MATERIALS

### **TABLES**

5.1 Recommended Management Actions for ACM

### **APPENDICES**

- A Operations and Maintenance (O&M) Procedures for ACM
- B Initial and Additional Cleaning Procedures

### IMPORTANT FOREWORD

The information presented herein, together with historical records for this location, satisfies the reporting requirements of the AHERA legislation and DODEA policy regarding Operations and Maintenance Manuals.

FOR A SUMMARY TABULATION OF WHERE ASBESTOS WAS FOUND, AND WHAT SHOULD BE DONE ABOUT IT, PLEASE REFER TO TABLE 5.1 PRINTED ON BLUETINTED PAPER.

Please also note that not all building materials have been tested. Examples of this may be materials which are hidden from view, inaccessible, or where sampling would be destructive. THEREFORE, THERE IS NO ASSURANCE THAT UNTESTED MATERIALS ARE ASBESTOS-FREE.

1.0 INTRODUCTION

The Department of Defense Education Activity (DODEA) has developed and implemented

an Asbestos Management Program to help ensure the safety of the occupants of Mannheim

American Elementary School and to comply with U.S. Environmental Protection Agency

(EPA) regulations issued in 1987 as required by the Asbestos Hazard Emergency Response

Act (AHERA).

Implementation of an Operations and Maintenance (O&M) Program is required whenever

materials with the potential to release asbestos fibers are found in the buildings. The primary

objective of this O&M Manual is to describe work practices and procedures that will prevent

the release of asbestos fibers during routine building maintenance and janitorial activities.

This O&M Manual describes initial and periodic cleaning procedures to be utilized in building

areas containing asbestos. In addition, it includes descriptions of maintenance and repair

procedures that must be followed by custodial and maintenance personnel who work with

asbestos-containing materials (ACM).

The Local Education Agency (LEA) Representative responsible for carrying out the O&M

Program, as described in the EPA regulations (Title 40 Code of Federal Regulations [CFR]

Part 763), is:

Ms. Liisa M. White

Department of Defense Education Activity

Logistics Division/Facilities Branch

4040 North Fairfax Drive

Arlington, VA 22203-1635

(703) 696-3850 (ext. 1801)

(703) 696-4030 (Fax)

1-1 2003 O&M Manual

The Asbestos Coordinator (AC) designated to carry out the duties of the LEA at Mannheim American Elementary School is:

Ms. Bonnie Bowen-Hannan Mannheim American Elementary School Unit 29938 APO AE 09086

Telephone: 49-621-722109 Telefax: 49-621-723905

1-2 2003 O&M Manual

### 2.0 BACKGROUND: ASBESTOS CHARACTERISTICS AND HEALTH EFFECTS

Asbestos is the common name for a group of naturally occurring fibrous mineral silicates. Because it is noncombustible and has low thermal conductivity, asbestos has been used extensively in the construction industry in a wide variety of applications.

There are six different types of asbestos: chrysotile, which accounts for approximately 90 percent of all commercially used asbestos; amosite and crocidolite, which are also commonly found in commercial and construction products; and tremolite, actinolite, and anthophyllite which are less commonly used. Asbestos was typically used as a component of materials, such as thermal insulation on pipes, boilers, and air handling ducts, and sprayed-on or troweled-on surfacing materials. Asbestos may also be found in miscellaneous materials such as fire-retardant blankets, cloths and textiles, roofing felts, plasters, cementitious tiles, floor tiles, and flooring adhesives. Damaged or deteriorated ACM may release microscopic fibers which can remain suspended in the air and potentially be inhaled into the lungs.

Inhalation of asbestos fibers has been linked to the development of certain respiratory diseases and of cancers of various internal organs including the lungs, esophagus, larynx, oral cavity, stomach, colon, and kidney. The three most common asbestos-related diseases are: asbestosis (a fibrous scarring of the lungs), lung cancer, and mesothelioma (a cancer of the lining of the chest or abdominal cavity). These diseases do not develop immediately after inhalation of asbestos fibers; it may be 20 years or more before symptoms appear. No safe level of asbestos exposure has yet been determined. Smoking, combined with exposure to asbestos, significantly increases the risk of developing respiratory diseases and cancers. Past studies of unprotected asbestos workers in occupational settings have shown that smoking combined with high levels of exposure to asbestos can increase the risk for development of asbestos-related diseases. An increase in risk of up to 50 times the risk level observed for non-smoking asbestos workers has been documented.

2-1

**OPERATIONS AND MAINTENANCE PROGRAM ELEMENTS** 3.0

The following sections describe the basic practices, procedures, and recommendations of

the O&M Program for this school or facility. Implementation of these program components is

required for compliance with AHERA. Appendix A contains specific maintenance and repair

instructions for the types of ACM identified in this school or facility.

3.1 **Informing Workers and Building Occupants** 

Maintenance workers, custodians, and building occupants must be informed annually of

asbestos materials in the building(s), scheduled and ongoing asbestos-related activities,

inspection results, management action(s), and periodic reinspection(s) and surveillance.

Short-term workers, such as telephone workers, utility workers, repairmen, and host-nation

contractors who could potentially come into contact with asbestos in this school must be

informed by the AC of the locations of all known or assumed ACM prior to working in those

areas.

Labels that warn of the presence of asbestos must be posted adjacent to both friable and

non-friable asbestos materials located in routine maintenance areas such as boiler rooms,

ceiling voids, and crawl spaces.

These labels must be posted for all friable and non-friable ACM including materials which

have been encapsulated, enclosed, or repaired. All warning labels must be displayed in

easily visible locations and must remain posted until the ACM has been completely removed.

Labels shall have a brightly colored background printed with the following warning in large

capital letters:

CAUTION: ASBESTOS HAZARD

DO NOT DISTURB WITHOUT PROPER TRAINING

AND EQUIPMENT

Labels written in both English and the host-nation language shall be posted.

3-1

2003 O&M Manual

### 3.2 <u>Training Requirements</u>

Prior to implementation of the O&M Program, AHERA requires that building maintenance and custodial staff receive two hours of asbestos awareness training. The maintenance and custodial staff must receive this training whether or not their work activities will involve contact with, or disturbance of, ACM. Also, all new staff must receive this 2-hour awareness training. For staff whose work activities may disturb ACM, 14 additional hours of training are required. New maintenance and custodial staff employees must receive the required training within 60 days of employment. For schools whose principals do not hire, supervise, or otherwise control building custodians or maintenance personnel, ways to implement the training requirements must be jointly explored with the supporting military installation and/or contracting agency. As outlined in the EPA regulations, training is required for the specific subjects listed below.

### **WORKER TRAINING OUTLINE**

### 2-Hour Awareness Training

- Asbestos uses and types
- Health effects associated with asbestos exposure
- ACM locations in each school building where employees work
- Recognition of ACM damage, deterioration, or delamination
- Name and telephone number of AC, availability and location of Asbestos Management Plan

### 14-Hour Additional Training

- Proper ACM handling methods
- Respiratory protection and personal protective equipment
- Review of:
  - Methods to determine management action completion
  - Small-scale, short-duration work activities (projects involving up to 3 square or linear feet of ACM)
  - Contractor accreditation
  - Transport and disposal of asbestos waste
- Worker protection
- Respirator fit-test and hands-on training in respiratory protective measures; work practice procedure review

**3-2** 2003 O&M Manual

### 3.3 Respiratory Protection Program

Before any O&M procedures are initiated, a Respiratory Protection Program, as outlined in Occupational Safety and Health Administration (OSHA) Regulation 29 CFR 1910.134 and 1910.1001, must be implemented and documented for all U.S. government employees whose work activities will involve contact with ACM. A written program must specify standard operating procedures for the use and maintenance of the respiratory protection equipment. The program must include respirator selection, fit-testing, and hands-on training of each employee required to wear a respirator. Respirators selected for use must be approved as protective against particulates (P100) by the National Institute for Occupational Safety and Health (NIOSH). A baseline medical examination and annual examinations as outlined in the OSHA regulation must be provided for each worker required to participate in the Respiratory Protection Program.

Respiratory protection must be utilized by all U.S. government employees when performing any project where the potential for exposure to asbestos fibers exist. The type of respiratory and personal protective equipment required by workers must be established for each area where an O&M activity is scheduled. Initial air monitoring samples must be obtained to determine the concentration of airborne asbestos fibers in each work area. Recommendations for respiratory protection must be consistent with the results of the initial air samples.

The foregoing U.S./OSHA-derived requirements may be waived for host-nation contractor personnel employed under host-nation jurisdiction. Host-nation contractor personnel must use respiratory protection in accordance with host-nation requirements.

### 3.4 Area Restrictions for ACM Related Work

Access to areas containing either friable or non-friable asbestos materials must be restricted before starting any O&M activity that could disturb the asbestos.

Depending on the O&M activity, restriction of an area will typically use the following procedures:

- Scheduling the activity during hours when the area will be unoccupied;
- Posting signs at all entrances into the area;
- Temporarily shutting off or modifying the air handling system;
- Limiting other sources of air movement in the area; and,
- On occasion, may include isolating the area with air-tight barriers.

Only trained personnel who are necessary to perform the maintenance activity are to be allowed into the restricted area.

### 3.5 Fiber Release Episodes - Procedures and Management

A fiber release episode may result from damage or deterioration of friable ACM. In the event of a fiber release episode, immediate action must be taken to protect the building occupants and workers from exposure to airborne fibers. Access to the affected area must be restricted. Hazard signs must be posted at all entry ways, and the air handling system to that area shut off. The use of appropriate respiratory protection and protective clothing is required by workers when responding to fiber release episodes.

### 3.5.1 Minor Fiber Release Episodes

A minor fiber release episode is the disturbance of no more than 3 square or linear feet or 0.3 square or 1 linear meter of friable ACM. If a minor fiber release episode should occur, the AC must be notified immediately. Properly trained maintenance personnel must take immediate action to clean up the falling or dislodged material and repair the damaged areas of ACM using the following procedures:

- Completely saturate all dislodged material with water;
- Place all dislodged materials into asbestos waste disposal containers;
- Wet wipe all surfaces which may of had dust/debris deposited on the surface;
- Thoroughly clean all surfaces in the area using a high efficiency particulate air (HEPA) vacuum;
- Dispose of all debris, filters, mopheads, and cloths in sealed, labeled, leak-tight containers; and,
- Repair the damaged area of asbestos material with an appropriate encapsulant or an
  asbestos free material such as spackle, plaster, cement, or insulation. If the damaged
  area cannot be repaired, physically isolate and restrict access to the area and initiate
  actions to remove the damaged ACM.

### 3.5.2 Major Fiber Release Episodes

A major fiber release episode is the disturbance of more than 3 square or linear feet or 0.3 square or 1 linear meter of friable ACM. If a major fiber release should occur, the AC and the Area Office must be notified immediately. The following actions must be taken:

- Restrict entry into the area and post signs at all entrances to prevent access by unauthorized persons; and,
- Temporarily shut off or modify the air handling system and limit other sources of air movement through the area.

Corrective management actions associated with major fiber release episodes must be designed, supervised, and conducted by appropriately qualified persons.

### 3.5.3 Decontamination Procedures

After handling any ACM, the proper decontamination of tools and personnel must be taken. Decontamination involves:

- Wet wiping any tools involved in the corrective management action.
- HEPA vacuuming protective clothing including hood and booties to remove accumulated asbestos debris.
- Removing protective clothing by turning the clothing inside-out, rolling into a ball, and disposing as asbestos-contaminated waste.
- Before removing respirator, wet wipe your face and the respirator.
- Thoroughly washing any exposed body part which may have come in contact with the ACM.

### 3.6 Waste Handling and Disposal

All asbestos-contaminated waste materials are to be handled, transported, and disposed of in a manner that prevents all visible emissions. All protective polyethylene disposable coveralls, respirator filters, vacuum cleaner, and wastewater used in O&M activities must be considered "asbestos wastes". All asbestos should be placed in 0.20 mm polyethylene bags that have pre-printed asbestos warning labels affixed to the bags. The AC should maintain a supply of these bags.

Asbestos-containing and asbestos-contaminated material must be placed into sealable 0.20 mm polyethylene bags while still wet. Do not overfill or place more than 10 kg into it. The bag should then be evacuated with a HEPA vacuum. It should be sealed by twisting the top 15 cm closed and wrapping with a minimum of two (2) layers of duct tape. Twist the top, fold over, and then apply a second wrap of duct tape. Clean the outside of the disposal bag by wet wiping. Finally, place the bag into a second properly labeled 0.20 mm polyethylene bag.

If sharp objects are to be disposed of, these should be placed in a puncture proof container such as a fiber board box and then bagged.

Excess wastewater generated from wetting procedures should be containerized and disposed of through a series of two (2) sock filters. The first filter is 100 micron pore size and filters out large particulates. The second filter is 5 micron pores and filters out smaller particulates. The water can then be disposed of as uncontaminated waste. The used filters must then be disposed of as asbestos-contaminated waste.

In addition, to load, transport, unload, and for final disposal of asbestos-containing and asbestos-contaminated materials, disposal should be in accordance with base procedures and the host-nation regulations and procedures.

### 3.7 <u>Maintenance and Repair Request Permit System</u>

The presence of ACM in buildings requires the establishment of a standardized and coordinated procedure for reviewing work order requests. This is necessary to: a) prevent unauthorized or untrained individuals from performing work that could potentially release asbestos fibers into the building environment, b) ensure that asbestos-related work activities, other than small-scale, short-duration projects (projects involving more than the amount of ACM specified in Appendix A of this manual), are designed and conducted by qualified persons. A program should be instituted in which all work requests, including those for renovations, repairs, etc., are first forwarded to the AC for approval.

The AC should review all work order requests to determine if the requested project activities could disturb ACM in the proposed work area. Absolutely no work activities should be permitted prior to this review process. For areas where intended work could cause asbestos fiber release, specific work procedures and equipment should be specified on the work permit.

### 3.8 Recordkeeping

The EPA Regulations require that O&M plans and records be maintained in both a central location at the facility's administrative office and at the Area Office. These records should be kept on file with the Asbestos Management Plan or entered into appropriate sections of the Asbestos Management Plan and include the following:

- For areas where all ACM has been removed, records pertaining to those areas must be kept for a period of at least 3 years following the next reinspection date.
- For material management actions:
  - Name/signature of person(s) who collected air samples for work completion verification
  - Air sample location and date
  - Name/address of laboratory performing the air sample analysis
  - Date/method/results of analysis
  - Name/signature of person(s) performing analysis
  - Laboratory certification verification
- For cleaning activities conducted in areas of ACM:
  - Date/name of person(s) conducting the cleaning
  - Location cleaned
  - Methods used
- For individuals requiring training as outlined in Section 3.2:
  - Name and job title
  - Date and location of training
  - Number of training hours completed
  - Date of last medical surveillance examination, where applicable

- For other activities under the scope of the O&M Program:
  - Name of persons performing the activity
  - Initiation/completion date of the specific activity
  - Location/description of the activity, including preventive measures
  - Name and location of storage or disposal site if ACM is removed during the activity
- For each fiber release episode:
  - Date/location of the episode
  - Repair method
  - Preventive measures or management action taken
  - Name/location of storage/disposal site if ACM is removed during the activity

### 3.9 Periodic Surveillance

All ACM identified in the building(s) shall be visually inspected by a designated person at least once every six months. The purpose of the surveillance is to determine if changes in the condition of the ACM have occurred and caused the ACM to become damaged or friable.

The AC will maintain a record of the surveillance and any observed changes of the material in the facility's Asbestos Management Plan.

### 4.0 EQUIPMENT REQUIREMENTS

The following equipment and materials are required, as applicable, for implementing the recommended O&M Program:

## RECOMMENDED INVENTORY FOR ASBESTOS O&M PROGRAM EQUIPMENT

Item	Quantity
"Danger Asbestos" Labeled Bags 75/Roll	1
6 mil Polyethylene Sheeting 10' X 100' Roll	1
Bridging Encapsulant 5 Gal Container	1
Duct Tape 10/Box	1
Garden Sprayer	1
Half Face Respirators	2
HEPA Filter Vacuum	1
P100 Respirator Cartridges 10/Box	1
Signs and Placards	1
Tyvek Suits 25/Box	1

#### 5.0 RECOMMENDED MANAGEMENT ACTIONS FOR ASBESTOS MATERIALS

Table 5.1 presents detailed recommended management actions for all ACM present during the 2003 AHERA Inspection (2003 inspection). The information on Table 5.1 is grouped by building for each building included in the 2003 inspection. Table 5.1 lists asbestos materials, identifies their location(s), friability, recommends material management action(s), lists material management procedures specific for each material, and notes if cleaning of the functional spaces where the material is located is required.

The recommended management action(s) provides detailed instructions for the management of the asbestos materials identified by the 2003 inspection. The Material Management Procedures, found in Appendix A, provide material-specific procedures for surveillance, labeling, and maintenance and repair of asbestos materials identified at Mannheim American Elementary School. Appendix B provides procedures for initial and additional cleaning of functional spaces where asbestos materials have been identified.

5-1 2003 O&M Manual

# MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

## TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS FOR ACM

BUILDING NUMBER	HOMO. MTRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	FRI- ABLE	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)	MATERIAL MANAGEMENT PROCEDURE	CLEANING REQUIRED
0697 (Unknown)	001	VINYL FLOOR TILE (1' X 1' BEIGE WITH WHITE AND BLACK SPECKS)	NO	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	THE ADHESIVE FOR THIS MATERIAL IS MATERIAL #036. THIS MATERIAL IS LOCATED BELOW EXISTING CARPET IN SOME LISTED LOCATIONS. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL         CONCERNING SAFE CUSTODIAL         PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS         MATERIAL UNDER THE ASBESTOS         MANAGEMENT PLAN.</li> </ol>	VINYL FLOOR TILE OR SHEETING	NO
0697 (Unknown)	019	SHEET GASKET (2" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	NO	HEAT DISTRIBUTION ROOM 1, HEAT DISTRIBUTION ROOM 2, MECHANICAL ROOM 1, MECHANICAL ROOM 2, MECHANICAL ROOM 3A, OLD BOILER ROOM		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>	GASKET MATERIAL AND FLEX CONNECTORS	NO
0697 (Unknown)	021	STALL PARTITIONS (GRAY CEMENT BOARD)	NO	GIRLS TOILET G3, OLD BOILER ROOM, 09D	ONE STALL PARTITION IN ROOM 09D IS DAMAGED AND NEEDS TO BE REMOVED. THERE IS ALSO ONE UNINSTALLED STALL PARTITION IN THE OLD BOILER ROOM THAT NEEDS TO BE REMOVED.	1. PORTIONS OF THIS MATERIAL SHOULD BE REMOVED WITHIN ONE YEAR OF RECEIPT OF THIS REPORT.  2. THIS MATERIAL COULD BE REMOVED BY QUALIFIED MAINTENANCE PERSONNEL WHO HAVE RECEIVED TRAINING IN SMALL SCALE, SHORT DURATION ABATEMENT PROJECTS.  3. FOR THE REMAINDER OF THIS MATERIAL, NO IMMEDIATE ABATEMENT IS REQUIRED.  4. CONSULT THE O & M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THE REMAINDER OF THIS MATERIAL.  5. CONTINUE SURVEILLANCE OF THE REMAINDER OF THIS MATERIAL.	ASBESTOS CEMENT ITEMS	NO
0697 (Unknown)	036	FLOOR ADHESIVE (BLACK, UNDER 1' X 1' BEIGE WITH WHITE AND BLACK SPECKS VINYL FLOOR TILE)	NO	03, 04A, 121C, 122C, 123C, 124C, 125C, 128C, 129C, 221C, 222C, 223C, 224C, 225C, 228C, 229C, 231D, 232D, 233D, 234D, 235D, 238D, 239D	THIS IS THE ADHESIVE FOR MATERIAL #001. PORTIONS OF THIS MATERIAL WERE ABATED DURING THE BUILDING RENOVATION PROJECT.	1. NO IMMEDIATE ABATEMENT REQUIRED. 2. CONSULT THE O & M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL. 3. CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.	FLOOR ADHESIVE (MASTIC)	NO

5 - 2 2003 O&M MANUAL

# MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

## TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS FOR ACM

BUILDING NUMBER	HOMO. MTRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	FRI- ABLE	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)	MATERIAL MANAGEMENT PROCEDURE	CLEANING REQUIRED
0697 (Unknown)	037	FLOOR ADHESIVE (BLACK, UNDER GREEN RAISED DOT RUBBER FLOOR SHEETING)	NO	CORRIDOR E, CORRIDOR H, STAIRWELL 1, 05 SUPPLY, 05A SUPPLY, 19, 20, 20A, 21, 22B, 22D, 22E, 27, 27B, 28, 28A, 29, 30, 30A, 31	THIS IS THE ADHESIVE FOR MATERIAL #005.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL         CONCERNING SAFE CUSTODIAL         PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS         MATERIAL UNDER THE ASBESTOS         MANAGEMENT PLAN.</li> </ol>	FLOOR ADHESIVE (MASTIC)	NO
0697 (Unknown)	039	WALL PLASTER (WHITE)	NO	CORRIDOR F		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>	SURFACING MATERIAL AND WALL, CEILING OR MISCELLANEOUS TILES	NO
0697 (Unknown)	041	FLOOR ADHESIVE (BROWN GLUE ON BLACK ADHESIVE, UNDER GREEN VINYL FLOOR SHEETING)	NO	CORRIDOR B2	AT THE TIME OF THE 1997, 2000, AND 2003 AHERA INSPECTIONS, THIS PREVIOUSLY IDENTIFIED MATERIAL COULD NOT BE LOCATED DUE TO THE APPLICATION OF A NEW CONCRETE FLOORING PRODUCT. IT WAS ASSUMED THAT THIS MATERIAL STILL REMAINS WITHIN THE BUILDING.	1. NO IMMEDIATE ABATEMENT REQUIRED. 2. CONSULT THE O & M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL. 3. CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.	FLOOR ADHESIVE (MASTIC)	NO
0697 (Unknown)	118	SHEET GASKET (4" - 6" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	NO	09 LOBBY, 27B	THIS MATERIAL IS LOCATED WITHIN THE PIPE CHASE INSIDE 09 LOBBY.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL         CONCERNING SAFE CUSTODIAL         PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS         MATERIAL UNDER THE ASBESTOS         MANAGEMENT PLAN.</li> </ol>	GASKET MATERIAL AND FLEX CONNECTORS	NO

5 - 3 2003 O&M MANUAL

# MANNHEIM AMERICAN ELEMENTARY SCHOOL HE 3469

## TABLE 5.1 - RECOMMENDED MANAGEMENT ACTIONS FOR ACM

BUILDING NUMBER	HOMO. MTRL. NO.	MATERIAL TYPE (MATERIAL DESCRIPTION)	FRI- ABLE	MATERIAL LOCATION(S)	COMMENTS	RECOMMENDED MANAGEMENT ACTION(S)	MATERIAL MANAGEMENT PROCEDURE	CLEANING REQUIRED
0697 (Unknown)	120	ROPE GASKET (WHITE)	NO	MECHANICAL ROOM 3A	THIS MATERIAL IS LOCATED ON PIPING AND IS USED AS A SPACER FOR CLAMPS.	<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL         CONCERNING SAFE CUSTODIAL         PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS         MATERIAL UNDER THE ASBESTOS         MANAGEMENT PLAN.</li> </ol>	GASKET MATERIAL AND FLEX CONNECTORS	NO
0697K (Unknown)	128	SHEET GASKET (4" DIAMETER, GRAY, ON PIPE FLANGE CONNECTIONS)	NO	MR		<ol> <li>NO IMMEDIATE ABATEMENT REQUIRED.</li> <li>CONSULT THE O &amp; M MANUAL CONCERNING SAFE CUSTODIAL PROCEDURES FOR THIS MATERIAL.</li> <li>CONTINUE SURVEILLANCE OF THIS MATERIAL UNDER THE ASBESTOS MANAGEMENT PLAN.</li> </ol>	GASKET MATERIAL AND FLEX CONNECTORS	NO

5 - 4 2003 O&M MANUAL

## **APPENDIX A**

# OPERATIONS AND MAINTENANCE (O&M) PROCEDURES FOR ACM

MATERIAL MANAGEMENT PROCEDURE FOR: Asbestos Cement Items (e.g., non-friable

heat shields, roofing, transite, firedampers, shutters, louvers)

INITIAL AND ADDITIONAL CLEANING: Refer to Table 7.1 in the Asbestos Management

Plan

**SURVEILLANCE:** Refer to requirements in Section 3.9

**LABELING:** Refer to requirements in Section 3.1

MAINTENANCE AND REPAIR PROCEDURES:

Damaged asbestos cement items such as heat shields, roofing, transite, firedampers, and

other similar materials should be replaced rather than repaired. Repair of damaged areas

1.0 square meter or less in size must be conducted if immediate removal and replacement is

not feasible. Material management actions for areas greater than 1.0 square meter in size

must be designed and conducted by qualified personnel.

Removal: To remove 1.0 square meter or 1.0 linear meter or less of asbestos cement

materials:

Thoroughly wet all surfaces, especially edges, using a spray bottle

Carefully remove material using only hand tools

Clean up area in accordance with Appendix B

Dispose of all debris in accordance with Section 3.6

Repair of Surface Areas: Repair of less than 1.0 square meter of asbestos cement surface

on floor, wall, or ceiling areas may be repaired by application of non-asbestos cement or

other similar patching compound.

Restricted Activities: Maintenance staff must avoid activities that will damage asbestos

cement materials. For example:

Do NOT cut, saw, or drill holes in asbestos cement products

Do **NOT** use power tools

Do NOT use abrasive materials on asbestos cement products

Do NOT use an ordinary vacuum or dry sweeping to clean up debris

## MATERIAL MANAGEMENT PROCEDURE FOR: Floor Adhesive (Mastic)

INITIAL AND ADDITIONAL CLEANING: Refer to Table 7.1 in the Asbestos Management

**SURVEILLANCE:** Refer to requirements in Section 3.9

LABELING: Not Applicable

Plan

## **MAINTENANCE AND REPAIR PROCEDURES:**

Projects accomplished by trained personnel should not exceed 1.0 square meter.

Removal: To remove floor tile adhesive:

- Soak material with hot water
- Remove damaged overlying tile with hand tools
- Remove adhesive material with hand tools
- Clean work area in accordance with Appendix B
- Dispose of all debris in accordance with Section 3.6

Restricted Activities: Maintenance staff must avoid activities that will damage floor adhesive:

- Never dry-grind floor adhesive
- Never dry-scrape floor adhesive

MATERIAL MANAGEMENT PROCEDURE FOR: Gasket Material and Flex Connectors

INITIAL AND ADDITIONAL CLEANING: Refer to Table 7.1 in the Asbestos Management

Plan

**SURVEILLANCE:** Refer to requirements in Section 3.9

LABELING: Refer to requirements in Section 3.1

#### **MAINTENANCE AND REPAIR PROCEDURES:**

The procedures below must be followed to protect building occupants if these materials require maintenance or repair.

Repair: Do not repair damaged gaskets or flex connectors. Replace with non-asbestos materials.

Removal: To remove and replace:

Shut down ventilation system, if applicable

- Isolate air duct section, if applicable
- Thoroughly wet exposed material using a spray bottle
- Loosen bolts on flanges holding material in place
- Carefully remove all material, periodically wetting with water from a spray bottle
- Thoroughly clean entire area in accordance with Appendix B
- Dispose of all debris in accordance with Section 3.6

<u>Restricted Activities:</u> Maintenance staff must avoid activities that will damage gasket cloth materials. For example:

- Do <u>NOT</u> cut, saw, or drill holes in gaskets or connectors
- Do <u>NOT</u> damage intact material
- Do NOT use an ordinary vacuum or dry sweeping to clean debris

MATERIAL MANAGEMENT PROCEDURE FOR: Surfacing Material and Wall, Ceiling, or

Miscellaneous Tiles

INITIAL AND ADDITIONAL CLEANING: Refer to Table 7.1 in the Asbestos Management

Plan

ASSOCIATED CLEANING:

In areas where friable sprayed-on or troweled-on ceiling or wall materials are located,

special cleaning procedures must be followed until all ACM has been removed.

Four times each year, all rugs and carpets must be vacuumed with a HEPA filtered

vacuum and then steam cleaned

All non-carpeted floors should be damp-mopped daily

**SURVEILLANCE:** Refer to requirements in Section 3.9

**LABELING:** Refer to requirements in Section 3.1

MAINTENANCE AND REPAIR PROCEDURES:

The following procedures must be followed to protect building occupants if wall or ceiling

surfacing materials or tiles require maintenance or repair. These procedures apply only to

activities involving 1.0 square meter or less of surfacing material.

1. Surfacing Material, Wall, or Ceiling (other than sprayed or troweled-on)

Repair: To repair damaged areas:

Patch holes with non-asbestos spackle or joint compound

Paint repaired surface with latex paint

Clean work area in accordance with Appendix B

Dispose of all debris in accordance with Section 3.6

## 2. <u>Sprayed-on or Troweled-on Surfacing Material</u>

<u>Repair:</u> To repair delaminated areas, the material should be removed according to the following procedures:

- Restrict access to area and conduct repair when building is not occupied
- Place a large disposable plastic sheet below delaminated area
- Spray affected area with water from a spray bottle
- Carefully remove loose or delaminated material with a putty knife and place into plastic bags
- Encapsulate scraped wall or ceiling with spray lacquer, being careful not to disturb intact material
- Clean work area in accordance with Appendix B
- Dispose of all debris and contaminated material in accordance with Section
   3.6

Surface blemishes should be repaired according to the following procedures:

- Place a large disposable plastic sheet below affected area
- Lightly spray affected area with lacquer paint
- Clean work area in accordance with Appendix B
- Dispose of debris in accordance with Section 3.6

#### 3. <u>Acoustical Wall or Ceiling Tile:</u>

<u>Repair:</u> Repair of acoustical tile is normally not required except for patching of small holes or abrasions to be covered for cosmetic reasons. Spray paint or putty can be applied to the damaged area.

Removal of Suspended Tile: To remove suspended acoustical tile:

- Wet tile using a spray bottle
- Carefully remove tile from metal grid
- Clean work area in accordance with Appendix B
- Dispose of tile in accordance with Section 3.6

Removal of Glued Tile: To remove glued acoustical tile from ceilings or wall:

- Wet tile using a spray bottle
- Carefully remove tile with a stiff-blade putty knife
- Keep all cut surfaces and edges damp using spray bottle
- Encapsulate remaining glue and adhered tile with latex paint
- Clean work area in accordance with Appendix B
- Dispose of all debris in accordance with Section 3.6
- 4. <u>Miscellaneous Tile Materials:</u> These materials should be removed and replaced when damaged. Repair is not recommended.

Removal of Miscellaneous Tile Materials: To remove 1.0 square meter or less of miscellaneous tile materials:

- Thoroughly wet all surfaces, especially edges, using a spray bottle
- Carefully remove material using only hand tools
- Clean up area in accordance with Appendix B
- Dispose of all debris in accordance with Section 3.6
- 5. For All Surfacing and Ceiling, Wall, or Miscellaneous Tile Materials:

<u>Prevent Damage:</u> Damage to surfacing material can be prevented by one or more of the following:

- Eliminate or minimize vibration to covered surfaces
- Eliminate airflow from ventilation ducts over or against surfaces
- Protect exposed areas from damage by barriers or protective guards
- Restrict activities which may result in impact damage to surfaces

<u>Restricted Activities:</u> Maintenance staff must avoid activities that will damage surfacing material. For example:

- Do NOT cut, saw, or drill holes in surfaces
- Do <u>NOT</u> damage intact material

- Do <u>NOT</u> hang or attach objects such as pictures, plant hangers or shelves from surface
- Do <u>NOT</u> spray surfaces with water for cleaning
- Do <u>NOT</u> use an ordinary vacuum or dry sweeping to clean debris

MATERIAL MANAGEMENT PROCEDURE FOR: Vinyl Floor Tile or Sheeting

INITIAL AND ADDITIONAL CLEANING: Refer to Table 7.1 in the Asbestos Management

SURVEILLANCE: Refer to requirements in Section 3.9

LABELING: Not Applicable

Plan

#### **MAINTENANCE AND REPAIR PROCEDURES:**

Damaged vinyl floor material should be replaced rather than repaired. Projects accomplished by trained personnel should not exceed 1.0 square meter.

Removal: To remove floor tile or section of vinyl sheeting:

- Soak material with hot water
- Remove tile or sheet with hand tools
- Clean work area in accordance with Appendix B
- Dispose of all debris in accordance with Section 3.6

<u>Restricted Activities:</u> Maintenance staff must avoid activities that will damage vinyl floor material. For example:

- Do <u>NOT</u> cut, saw, or drill holes in vinyl material
- Do <u>NOT</u> use power sanders or chippers
- Do NOT perform dry stripping
- Do <u>NOT</u> use power disc strippers with steel wool pads
- Buff at slow speeds (175-190 RPM) with a low abrasive pad

## APPENDIX B

# **INITIAL AND ADDITIONAL CLEANING PROCEDURES**

INITIAL AND ADDITIONAL CLEANING PROCEDURES

For each area where friable ACM, damaged or significantly damaged thermal system ACM

insulation, or damaged friable suspected ACM, was identified during the inspection, an initial

cleaning is required. This cleaning must occur prior to any management actions, other than

O&M activities or repairs, unless an equivalent cleaning has been performed within the

previous 6-month period.

Table 5.1 identifies the locations requiring initial and additional cleaning.

Before any cleanup or O&M procedures are initiated, all persons conducting the cleanup

must be examined by a physician to verify that each person can safely wear a respirator.

Respirators must be fit-tested for each individual to ensure that the person will not be

breathing contaminated air. During all cleanup and O&M procedures, the respirators will be

worn at all times.

1. Friable Surfacing ACM Area Cleaning

The following equipment is required for conducting cleaning operations:

HEPA filtered vacuum

Steam carpet cleaner

Large 6 mil plastic bags

Cloths and mops

Spray bottle

Half and full facepiece air-purifying respirators with dual replaceable

P100 cartridges

Protective clothing (Tyvek)

NOTE: Exercise caution when using water around electrical fixtures and outlets.

B-1

2003 O&M Manual

All carpets in rooms containing ACM should be cleaned first with a HEPA filtered vacuum and then by a steam cleaner. All curtains and books exposed to the ACM should be HEPA vacuumed. Vacuum bags and filters should be placed in sealed 6 mil plastic bags for disposal.

Wet mop all other floors in the rooms where ACM is located. All shelves and other horizontal surfaces should be wiped with damp cloths. Use a mist spray bottle to keep the cloths damp. Cloths and mopheads must then be discarded in sealed and labeled 6 mil plastic bags.

The following cleaning procedures must be conducted whenever asbestos-containing debris is discovered.

- If there is visible asbestos debris in the area, immediately put on a respirator and continue the cleaning procedures as described in this section.
- Spray with water any debris found near friable surfacing ACM and place the debris in labeled 6 mil plastic bags using a dust pan. Thoroughly rinse the dust pan with water in a utility sink. Immediately report the presence of debris to the AC. DO NOT SWEEP ASBESTOS DEBRIS WITHOUT THOROUGHLY WETTING IT FIRST.
- HEPA vacuum and steam clean all carpets.
- Wet mop all other floors and wipe all other horizontal surfaces with damp cloths.
- Dispose of all debris, filters, mopheads, and cloths in labeled 6 mil plastic bags in accordance with local regulations for disposal of asbestos waste.

## 2. Thermal System Insulation Cleaning

The following equipment is required for conducting cleaning operations:

- HEPA filtered vacuum
- Steam carpet cleaner
- Large 6 mil plastic bags
- Cloths and mops
- Spray bottle
- Half and full facepiece air-purifying respirators with dual replaceable P100 cartridges
- Protective clothing

All floors should be HEPA vacuumed then wet mopped in the rooms where the pipe or boiler/tank insulation is located. HEPA vacuum and steam clean all carpets contaminated with asbestos-containing thermal system insulation. All shelves and other horizontal surfaces should be wiped with damp cloths. Use a mist spray bottle to keep the cloths damp. Air filters that are potentially contaminated by ACM fibers should be sprayed with water, removed carefully, and properly bagged prior to disposal. Air handling equipment, including ducts and room areas supplied by the potentially contaminated system, must be thoroughly cleaned using HEPA-equipped vacuums prior to filter replacement. Cloths, mopheads, and filters should be discarded in sealed, labeled 6 mil plastic bags according to local regulations for removal and disposal of asbestos waste.

#### 3. Cleaning Procedures for Miscellaneous ACM Areas

Most ACM that is not either surfacing material or thermal system insulation is non-friable. Items such as vinyl asbestos floor tiles, ceiling tiles, transite pipes, and gaskets are examples of materials that are usually considered to be non-friable. Specialized cleaning procedures are not necessary for these materials unless they have sustained damage. If these materials are damaged, the cleaning procedures described for thermal system insulation should be implemented until repair of the material has been completed.

B-3 2003 O&M Manual